



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 21.JAN.2022 19:11:30

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 21.JAN.2022 19:11:52

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 21.JAN.2022 19:12:14

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 21.JAN.2022 19:12:35

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 21.JAN.2022 19:12:56

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 21.JAN.2022 19:13:13

Band 2_3 MHz_High_QPSK_RB15#0




Date: 21.JAN.2022 19:13:32

Band 2_3 MHz_High_16QAM_RB15#0




Date: 21.JAN.2022 19:13:49

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 19:14:11

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 19:14:28

Band 2_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 19:14:50

Band 2_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 19:15:11

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 22:28:41

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 22:29:09

Band 2_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 19:16:15

Band 2_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 19:16:35

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 19:17:03

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 19:17:27

Band 2_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 19:17:53

Band 2_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 19:18:17

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 19:18:48

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 19:19:12

Band 2_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 22:30:50

Band 2_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 19:20:01

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 21.JAN.2022 22:32:09

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 21.JAN.2022 19:20:43

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 21.JAN.2022 19:21:02

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 21.JAN.2022 19:21:19

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 21.JAN.2022 19:21:41

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 21.JAN.2022 19:22:02

Band 4_3 MHz_High_QPSK_RB15#0




Date: 21.JAN.2022 19:22:20

Band 4_3 MHz_High_16QAM_RB15#0




Date: 21.JAN.2022 19:22:41

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 19:23:03

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 19:23:23

Band 4_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 19:23:45

Band 4_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 19:24:06

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 19:24:33

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 22:33:14

Band 4_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 19:25:17

Band 4_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 19:25:37

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 19:26:05

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 19:26:29

Band 4_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 19:26:55

Band 4_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 19:27:22

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 19:27:50

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 19:28:18

Band 4_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 19:28:43

Band 4_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 19:29:07

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 21.JAN.2022 19:29:32

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 21.JAN.2022 19:29:53

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 21.JAN.2022 19:30:11

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 21.JAN.2022 19:30:32

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 21.JAN.2022 19:30:57

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 21.JAN.2022 19:31:14

Band 5_3 MHz_High_QPSK_RB15#0




Date: 21.JAN.2022 19:31:42

Band 5_3 MHz_High_16QAM_RB15#0




Date: 21.JAN.2022 19:31:59

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 22:35:25

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 19:32:42

Band 5_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 19:33:00

Band 5_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 19:33:21

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 19:33:45

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 19:34:05

Band 5_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 19:34:27

Band 5_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 19:34:50

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 19:35:15

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 19:35:33

Band 7_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 19:35:55

Band 7_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 19:36:15

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 19:36:39

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 19:36:59

Band 7_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 19:37:20

Band 7_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 19:37:43

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 19:38:11

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 19:38:35

Band 7_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 19:39:00

Band 7_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 19:39:24

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 19:39:53

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 19:40:18

Band 7_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 19:40:43

Band 7_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 19:41:07

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 21:18:06

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 22:19:30

Band 38_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 21:18:58

Band 38_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 21:19:22

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 21:19:48

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 22:26:44

Band 38_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 21:20:28

Band 38_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 21:20:51

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 21:21:22

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 21:21:53

Band 38_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 21:22:30

Band 38_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 21:23:01

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 21:23:32

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 21:23:59

Band 38_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 21:24:27

Band 38_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 21:25:04

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 21:25:41

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 21:26:11

Band 41_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 21:26:32

Band 41_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 21:26:56

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 21:27:26

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 21:27:49

Band 41_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 21:28:12

Band 41_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 21:28:35

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 22:23:04

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 21:29:53

Band 41_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 22:24:12

Band 41_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 21:30:48

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 21:31:23

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 21:31:50

Band 41_20 MHz_High_QPSK_RB100#0



Date: 21.JAN.2022 21:32:22

Band 41_20 MHz_High_16QAM_RB100#0



Date: 21.JAN.2022 21:32:52