



80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB1@0 -36.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:37:05

80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB1@0 -46.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:36:18

80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB1@216 -37.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:38:25

80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB1@216 -46.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:37:38

80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB216@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:38:59

80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB216@0 -36.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:39:45

80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:32:49

80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:32:05

80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@216 -37.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:45:33

80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@216 -47.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:44:46

80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB216@0 -37.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:46:53

80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB216@0 -47.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:46:06

80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:35:01

80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:35:45

80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB1@216 -37.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:52:40

80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB1@216 -46.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:51:54

80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB216@0 -37.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:54:01

80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB216@0 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:53:14

90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@0 -47.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:55:35

90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@0 -37.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:56:23

90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@244 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:56:56

90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@244 -37.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:57:43

90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB243@0 -36.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:59:04

90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB243@0 -47.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:58:16

90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:02:31

90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -36.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:03:19

90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@244 -36.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:04:40

90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@244 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:03:52

90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB243@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:06:00

90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB243@0 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:05:13

90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB1@0 -37.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:08:04

90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB1@0 -46.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:07:16

90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB1@244 -46.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:08:37

90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB1@244 -37.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:09:24

90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB243@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:09:59

90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB243@0 -36.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:10:46

100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB1@0 -46.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:12:02

100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB1@0 -37.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:12:50

100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB1@272 -46.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:13:24

100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB1@272 -37.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:14:11

100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB270@0 -36.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:15:32

100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB270@0 -47.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:14:45

100MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:38:00

100MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:37:16

100MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@272 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:19:55

100MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@272 -46.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:19:07

100MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB270@0 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:20:29

100MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB270@0 -37.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:21:16

100MHz_30kHz_2640MHz_DFT-s-OFDM QPSK_RB1@0 -37.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:23:41

100MHz_30kHz_2640MHz_DFT-s-OFDM QPSK_RB1@0 -46.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:22:54

100MHz_30kHz_2640MHz_DFT-s-OFDM QPSK_RB1@272 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:24:15

100MHz_30kHz_2640MHz_DFT-s-OFDM QPSK_RB1@272 -37.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:25:02

100MHz_30kHz_2640MHz_DFT-s-OFDM QPSK_RB270@0 -36.70 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:26:23


100MHz_30kHz_2640MHz_DFT-s-OFDM QPSK_RB270@0 -47.23 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:25:36


n66

5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:27:20

5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:27:56

5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB1@24 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:28:30

5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB1@24 -36.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:29:07

5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB25@0 -46.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:29:40

5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB25@0 -36.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:30:16

5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -36.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:34:01

5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -47.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:33:24

5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@24 -36.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:35:10

5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@24 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:34:34

5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB25@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:35:44

5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB25@0 -36.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:36:21

5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:39:33

5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:40:08

5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB1@24 -47.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:40:43

5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB1@24 -36.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:41:20

5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB25@0 -47.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:41:54

5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB25@0 -37.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:42:30

10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:45:46

10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB1@0 -36.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:46:22

10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB1@51 -36.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:47:33

10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB1@51 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:46:56

10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB50@0 -37.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:48:44

10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB50@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:48:07

10MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:50:19

10MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -36.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:50:56

10MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@51 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:51:30

10MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@51 -36.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:52:08

10MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB50@0 -47.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:52:42

10MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB50@0 -36.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:53:18

10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB1@0 -47.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:56:43

10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB1@0 -36.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:57:20

10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB1@51 -36.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:58:31

10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB1@51 -47.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:57:54

10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB50@0 -36.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:59:41

10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB50@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 05:59:05

15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:03:36

15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:03:00

15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB1@78 -36.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:04:46

15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:04:10

15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB75@0 -36.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:05:56

15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:05:20

15MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -36.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:09:48

15MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -47.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:09:11

15MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@78 -37.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:11:00

15MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@78 -46.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:10:23

15MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB75@0 -47.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:11:34

15MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB75@0 -36.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:12:09

15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:39:24

15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:38:50

15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:16:06

15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB1@78 -36.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:16:43

15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB75@0 -47.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:17:16

15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB75@0 -36.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:17:53

20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB1@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:43:17

20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB1@0 -36.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:43:51

20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB1@105 -36.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:23:35

20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB1@105 -47.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:22:59

20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB100@0 -36.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:24:45

20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB100@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:24:08

20MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -47.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:28:00

20MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -36.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:28:38

20MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@105 -36.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:29:48

20MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@105 -47.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:29:11

20MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB100@0 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:30:21

20MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB100@0 -36.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:30:58

20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:44:56

20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB1@0 -36.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:45:30

20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB1@105 -36.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:37:02

20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB1@105 -47.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:36:24

20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB100@0 -46.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:37:36

20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB100@0 -36.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:38:12

25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:40:38

25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:40:00

25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB1@132 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:41:12

25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB1@132 -36.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:41:49

25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB128@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:42:27

25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB128@0 -36.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:43:07

25MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -37.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:47:43

25MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -47.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:47:09

25MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@132 -36.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:48:15

25MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@132 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:47:31

25MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB128@0 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:48:57

25MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB128@0 -36.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:49:37

25MHz_15kHz_1767.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:48:48

25MHz_15kHz_1767.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:49:21

25MHz_15kHz_1767.5MHz_DFT-s-OFDM QPSK_RB1@132 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:53:50

25MHz_15kHz_1767.5MHz_DFT-s-OFDM QPSK_RB1@132 -36.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:54:27

25MHz_15kHz_1767.5MHz_DFT-s-OFDM QPSK_RB128@0 -47.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:55:01

25MHz_15kHz_1767.5MHz_DFT-s-OFDM QPSK_RB128@0 -35.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 06:55:38

30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB1@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:53:27

30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB1@0 -36.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:54:01

30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB1@159 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:00:51

30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB1@159 -36.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:01:29

30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB160@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:02:03

30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB160@0 -37.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:02:38

30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -36.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:58:52

30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -46.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:58:20

30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@159 -47.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:06:39

30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@159 -36.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:07:17

30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB160@0 -36.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:08:28

30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB160@0 -46.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:07:52

30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB1@0 -36.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:12:29

30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB1@0 -47.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:11:53

30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB1@159 -36.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:13:41

30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB1@159 -47.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:13:03

30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB160@0 -36.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:14:52

30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB160@0 -46.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:14:15

40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@0 -36.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:16:46

40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@0 -47.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:16:09

40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@215 -46.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:17:21

40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@215 -35.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:17:58

40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB216@0 -46.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:18:34

40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB216@0 -36.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:19:10

40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -47.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:22:24

40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0 -35.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:23:01

40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@215 -47.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:23:35

40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@215 -36.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:24:12

40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB216@0 -46.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:24:47

40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB216@0 -36.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:25:24

40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@0 -36.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:29:31

40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@0 -47.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:28:55

40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@215 -36.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:30:42

40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@215 -47.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:30:06

40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB216@0 -36.81 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:31:55


40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB216@0 -47.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 07:31:17


n7

5MHz_15kHz_2502.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:34:17

5MHz_15kHz_2502.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:35:02

5MHz_15kHz_2502.5MHz_DFT-s-OFDM QPSK_RB1@24 -46.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:35:33

5MHz_15kHz_2502.5MHz_DFT-s-OFDM QPSK_RB1@24 -37.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:36:18

5MHz_15kHz_2502.5MHz_DFT-s-OFDM QPSK_RB25@0 -36.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:37:35

5MHz_15kHz_2502.5MHz_DFT-s-OFDM QPSK_RB25@0 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:36:50

5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -47.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 17.MAY.2024 21:39:17

5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -37.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 17.MAY.2024 21:40:02

5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@24 -36.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 17.MAY.2024 21:41:44

5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@24 -46.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 17.MAY.2024 21:40:59

5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB25@0 -37.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 17.MAY.2024 21:43:00

5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB25@0 -47.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 17.MAY.2024 21:42:15

5MHz_15kHz_2567.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:46:39

5MHz_15kHz_2567.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:45:54

5MHz_15kHz_2567.5MHz_DFT-s-OFDM QPSK_RB1@24 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:47:10

5MHz_15kHz_2567.5MHz_DFT-s-OFDM QPSK_RB1@24 -37.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:47:56

5MHz_15kHz_2567.5MHz_DFT-s-OFDM QPSK_RB25@0 -46.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:48:27

5MHz_15kHz_2567.5MHz_DFT-s-OFDM QPSK_RB25@0 -37.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:49:13

10MHz_15kHz_2505MHz_DFT-s-OFDM QPSK_RB1@0 -37.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:51:39

10MHz_15kHz_2505MHz_DFT-s-OFDM QPSK_RB1@0 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:50:53

10MHz_15kHz_2505MHz_DFT-s-OFDM QPSK_RB1@51 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:52:56

10MHz_15kHz_2505MHz_DFT-s-OFDM QPSK_RB1@51 -42.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:52:10

10MHz_15kHz_2505MHz_DFT-s-OFDM QPSK_RB50@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:53:43

10MHz_15kHz_2505MHz_DFT-s-OFDM QPSK_RB50@0 -36.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:54:38

10MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -46.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:57:29

10MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:58:23

10MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@51 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:00:06

10MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@51 -47.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 21:59:11

10MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB50@0 -36.42 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:01:48

10MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB50@0 -46.98 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:00:53