



10MHz_15kHz_2565MHz_DFT-s-OFDM QPSK_RB1@0 -47.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:04:40

10MHz_15kHz_2565MHz_DFT-s-OFDM QPSK_RB1@0 -36.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:05:25

10MHz_15kHz_2565MHz_DFT-s-OFDM QPSK_RB1@51 -37.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:07:07

10MHz_15kHz_2565MHz_DFT-s-OFDM QPSK_RB1@51 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:06:22

10MHz_15kHz_2565MHz_DFT-s-OFDM QPSK_RB50@0 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:07:38

10MHz_15kHz_2565MHz_DFT-s-OFDM QPSK_RB50@0 -36.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:08:23

15MHz_15kHz_2507.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:10:49

15MHz_15kHz_2507.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:11:34

15MHz_15kHz_2507.5MHz_DFT-s-OFDM QPSK_RB1@78 -36.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:12:50

15MHz_15kHz_2507.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:12:05

15MHz_15kHz_2507.5MHz_DFT-s-OFDM QPSK_RB75@0 -36.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:14:32

15MHz_15kHz_2507.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:13:47

15MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:17:02

15MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -47.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:16:17

15MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@78 -37.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:18:18

15MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@78 -46.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:17:33

15MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB75@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:18:50

15MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB75@0 -37.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:19:36

15MHz_15kHz_2562.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:22:46

15MHz_15kHz_2562.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:23:32

15MHz_15kHz_2562.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:24:48

15MHz_15kHz_2562.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:24:02

15MHz_15kHz_2562.5MHz_DFT-s-OFDM QPSK_RB75@0 -36.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:26:05

15MHz_15kHz_2562.5MHz_DFT-s-OFDM QPSK_RB75@0 -47.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:25:20

20MHz_15kHz_2510MHz_DFT-s-OFDM QPSK_RB1@0 -47.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:27:32

20MHz_15kHz_2510MHz_DFT-s-OFDM QPSK_RB1@0 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:28:18

20MHz_15kHz_2510MHz_DFT-s-OFDM QPSK_RB1@105 -37.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:30:00

20MHz_15kHz_2510MHz_DFT-s-OFDM QPSK_RB1@105 -47.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:29:15

20MHz_15kHz_2510MHz_DFT-s-OFDM QPSK_RB100@0 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:30:31

20MHz_15kHz_2510MHz_DFT-s-OFDM QPSK_RB100@0 -37.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:31:16

20MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -33.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:32:27

20MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0 -36.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:33:12

20MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@105 -47.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:33:44

20MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@105 -37.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:34:30

20MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB100@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:35:02

20MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB100@0 -36.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:35:47

20MHz_15kHz_2560MHz_DFT-s-OFDM QPSK_RB1@0 -37.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:41:00

20MHz_15kHz_2560MHz_DFT-s-OFDM QPSK_RB1@0 -47.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:40:14

20MHz_15kHz_2560MHz_DFT-s-OFDM QPSK_RB1@105 -46.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:41:32

20MHz_15kHz_2560MHz_DFT-s-OFDM QPSK_RB1@105 -37.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:42:18

20MHz_15kHz_2560MHz_DFT-s-OFDM QPSK_RB100@0 -37.12 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:43:35


20MHz_15kHz_2560MHz_DFT-s-OFDM QPSK_RB100@0 -47.33 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 17.MAY.2024 22:42:49


n77_1

10MHz_15kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -37.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:00:11

10MHz_15kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -47.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 21:59:16

10MHz_15kHz_3455MHz_DFT-s-OFDM QPSK_RB1@51 -43.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:05:19

10MHz_15kHz_3455MHz_DFT-s-OFDM QPSK_RB1@51 -46.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:02:08

10MHz_15kHz_3455MHz_DFT-s-OFDM QPSK_RB50@0 -46.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:06:12

10MHz_15kHz_3455MHz_DFT-s-OFDM QPSK_RB50@0 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:07:07

10MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:08:18

10MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -38.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 22:09:12

10MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@51 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:01:10

10MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@51 -37.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:02:08

10MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0 -37.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:04:05

10MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0 -47.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:03:07

10MHz_15kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 19.MAY.2024 09:05:03

10MHz_15kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -38.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 19.MAY.2024 09:06:01

10MHz_15kHz_3545MHz_DFT-s-OFDM QPSK_RB1@51 -46.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 19.MAY.2024 09:07:00

10MHz_15kHz_3545MHz_DFT-s-OFDM QPSK_RB1@51 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 19.MAY.2024 09:07:57

10MHz_15kHz_3545MHz_DFT-s-OFDM QPSK_RB50@0 -46.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 19.MAY.2024 09:08:57

10MHz_15kHz_3545MHz_DFT-s-OFDM QPSK_RB50@0 -37.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 19.MAY.2024 09:09:54

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -47.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:31:08

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -36.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:32:02

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23 -37.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:34:08

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23 -47.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:33:14

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -46.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:34:58

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -37.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:35:52

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:36:43

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:37:36

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:43:54

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23 -37.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:44:48

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:46:14

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0 -37.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:47:08

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -47.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:47:57

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -37.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:48:51

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:50:34

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -46.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:49:41

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -46.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:51:24

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -37.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:52:18

15MHz_15kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:13:16

15MHz_15kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:14:18

15MHz_15kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:17:31

15MHz_15kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:18:32

15MHz_15kHz_3457.5MHz_DFT-s-OFDM QPSK_RB75@0 -47.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:21:37

15MHz_15kHz_3457.5MHz_DFT-s-OFDM QPSK_RB75@0 -37.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:22:35

15MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:26:34

15MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:25:37

15MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@78 -37.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:28:31

15MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@78 -46.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:27:33

15MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0 -37.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:30:28

15MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0 -46.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 09:29:31

15MHz_15kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:19:09

15MHz_15kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:20:02

15MHz_15kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:38:43

15MHz_15kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:39:37

15MHz_15kHz_3542.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 21.MAY.2024 17:30:09

15MHz_15kHz_3542.5MHz_DFT-s-OFDM QPSK_RB75@0 -38.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 21.MAY.2024 17:31:04

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -38.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:54:21

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:53:27

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37 -46.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:55:10

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:56:03

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:56:53

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:57:46

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:10:45

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:11:39

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37 -46.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:12:28

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37 -37.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:13:22

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0 -37.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:15:05

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:14:11

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:16:48

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:15:55

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:18:51

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@37 -41.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:17:57

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:19:41

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:20:34

20MHz_15kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0 -37.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:41:20

20MHz_15kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0 -41.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:40:27

20MHz_15kHz_3460MHz_DFT-s-OFDM QPSK_RB1@105 -37.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:26:51

20MHz_15kHz_3460MHz_DFT-s-OFDM QPSK_RB1@105 -47.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:25:58

20MHz_15kHz_3460MHz_DFT-s-OFDM QPSK_RB100@0 -47.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:27:41

20MHz_15kHz_3460MHz_DFT-s-OFDM QPSK_RB100@0 -38.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:28:35

20MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:30:50

20MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -38.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:31:24

20MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:32:12

20MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -37.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:33:06

20MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -38.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:34:48

20MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -46.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:33:55

20MHz_15kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0 -37.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:36:53

20MHz_15kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:35:59

20MHz_15kHz_3540MHz_DFT-s-OFDM QPSK_RB1@105 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:38:19

20MHz_15kHz_3540MHz_DFT-s-OFDM QPSK_RB1@105 -37.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:39:12

20MHz_15kHz_3540MHz_DFT-s-OFDM QPSK_RB100@0 -37.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:41:30

20MHz_15kHz_3540MHz_DFT-s-OFDM QPSK_RB100@0 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:40:37

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0 -37.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:22:18

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0 -40.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:21:24

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:24:00

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50 -43.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:23:07

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0 -27.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:24:54

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:25:47

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 09:26:38

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 09:27:31

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50 -37.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 09:29:34

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50 -47.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 09:28:40

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0 -37.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 09:31:17

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0 -42.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 09:30:24

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0 -37.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:33:13

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0 -34.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:32:19

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:34:02

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50 -38.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:34:57

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0 -47.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:35:58

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0 -37.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:36:57

30MHz_15kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0 -47.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:42:09

30MHz_15kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0 -37.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 08:43:03

30MHz_15kHz_3465MHz_DFT-s-OFDM QPSK_RB1@159 -38.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:45:46

30MHz_15kHz_3465MHz_DFT-s-OFDM QPSK_RB1@159 -46.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:44:53

30MHz_15kHz_3465MHz_DFT-s-OFDM QPSK_RB160@0 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:46:37

30MHz_15kHz_3465MHz_DFT-s-OFDM QPSK_RB160@0 -37.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:47:30

30MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:48:42

30MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:49:35

30MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@159 -37.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:51:19

30MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@159 -46.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:50:25

30MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB160@0 -38.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:53:03

30MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB160@0 -47.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:52:09

30MHz_15kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0 -47.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 01:53:53

30MHz_15kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 01:54:47

30MHz_15kHz_3535MHz_DFT-s-OFDM QPSK_RB1@159 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 01:55:37

30MHz_15kHz_3535MHz_DFT-s-OFDM QPSK_RB1@159 -37.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 01:56:31

30MHz_15kHz_3535MHz_DFT-s-OFDM QPSK_RB160@0 -46.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 01:57:46

30MHz_15kHz_3535MHz_DFT-s-OFDM QPSK_RB160@0 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 01:58:40

40MHz_15kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 01:59:30

40MHz_15kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -37.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:00:23

40MHz_15kHz_3470MHz_DFT-s-OFDM QPSK_RB1@215 -37.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:02:06

40MHz_15kHz_3470MHz_DFT-s-OFDM QPSK_RB1@215 -46.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:01:13

40MHz_15kHz_3470MHz_DFT-s-OFDM QPSK_RB216@0 -46.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:02:56

40MHz_15kHz_3470MHz_DFT-s-OFDM QPSK_RB216@0 -37.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:03:50

40MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:04:39

40MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -38.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:05:33

40MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@215 -47.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:06:22

40MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@215 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:07:16

40MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -46.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:08:05

40MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -37.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:08:59

40MHz_15kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -37.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:10:43

40MHz_15kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -47.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:09:49

40MHz_15kHz_3530MHz_DFT-s-OFDM QPSK_RB1@215 -37.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:12:27

40MHz_15kHz_3530MHz_DFT-s-OFDM QPSK_RB1@215 -46.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:11:33

40MHz_15kHz_3530MHz_DFT-s-OFDM QPSK_RB216@0 -46.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:13:17

40MHz_15kHz_3530MHz_DFT-s-OFDM QPSK_RB216@0 -37.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:14:11

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -46.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:38:00

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -37.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:38:59

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105 -47.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:40:02

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:40:59

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -43.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:42:01

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -38.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:43:00

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:45:00

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:44:02

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -47.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:45:53

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:46:47

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -47.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:47:37

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -37.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:48:30

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -37.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:50:14

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -47.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:49:20

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -46.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:51:03

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -37.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:51:57

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -37.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:53:40

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -42.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:52:47

50MHz_15kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:15:01

50MHz_15kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -37.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:15:55

50MHz_15kHz_3475MHz_DFT-s-OFDM QPSK_RB1@269 -46.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:16:47

50MHz_15kHz_3475MHz_DFT-s-OFDM QPSK_RB1@269 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:17:41

50MHz_15kHz_3475MHz_DFT-s-OFDM QPSK_RB270@0 -47.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:18:31

50MHz_15kHz_3475MHz_DFT-s-OFDM QPSK_RB270@0 -37.35 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
 Date: 22.MAY.2024 02:19:25