



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:06:26

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:06:37

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:06:57

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:07:07

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:07:24

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:07:35

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:07:52

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:08:03

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:08:19

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:08:30

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:08:50

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:09:00

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:09:18

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:09:29

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:09:48


### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:09:59




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:10:19

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:10:30

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:10:53

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:11:04

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:11:26

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:11:36

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:11:55

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:12:06

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:12:33

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:12:44

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:13:07

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:13:18

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:13:41

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:13:52

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:14:16


### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:14:27




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:14:53

### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:15:04

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:15:27

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:15:38

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:15:59

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:16:09

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:16:26

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:16:36

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:16:56

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:17:07

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:17:25

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:17:35

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:17:52

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:18:03

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:18:19


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:18:33




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:18:54

### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:19:05

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:19:25

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:19:35

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:19:52

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:20:02

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:20:22

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:20:33

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:20:51

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:21:02

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:21:21

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:21:32

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:21:56

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:22:06

### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:22:33


### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:22:43




### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:23:10

### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:23:20

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:23:45

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:23:55

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:24:18

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:24:29

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:24:55

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:25:06

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:25:27

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:25:37

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:25:57

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:26:07

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:26:27

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:26:41

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:27:02


### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 2.DEC.2021 11:27:12




### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:27:29

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:27:39

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:27:56

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:28:07

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:28:27

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:28:38

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:28:54

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:29:05

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:29:22

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:29:32

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:29:52

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:30:03

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:30:21

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 2.DEC.2021 11:30:32

### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:30:54


### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 2.DEC.2021 11:31:05




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:31:25

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:31:36

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:31:53

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:32:03

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:32:23

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:32:33

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:32:53

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:33:04

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:33:23

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:33:33

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:33:55

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:34:06

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:34:30

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:34:40

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:35:07


### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 2.DEC.2021 11:35:17




### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:35:41

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:35:51

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:36:15

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:36:26

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:36:49

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:37:00

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:37:23

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 11:37:34

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:20:00

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:20:11

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:20:28

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:20:38

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:20:58

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:21:09

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 13:21:29


### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 2.DEC.2021 13:21:40




### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:21:59

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:22:09

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:22:28

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:22:39

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:23:04

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:23:14

### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:23:38

### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:23:48

### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:24:15

### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:24:25

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:24:53

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:25:03

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 13:25:27

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.DEC.2021 13:25:37

### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 13:26:01


### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 2.DEC.2021 13:26:11




Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:47:47

Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:48:16

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:48:45

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:49:07

Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:49:33

Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:49:59

Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:50:30

Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:50:50

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:51:23

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:51:52

Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:52:28

Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:52:54

Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:53:28

Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:53:57

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 1.DEC.2021 17:54:29


Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 1.DEC.2021 17:54:58




Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:55:27

Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:55:56

Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:56:30

Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:56:55

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:57:28

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:57:54

Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2021 17:58:27

Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2021 17:58:49

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:37:51

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:38:02

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:38:19

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:38:29

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:38:46

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:38:57

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:39:14


### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:39:25




### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:39:45

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:39:55

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:40:12

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:40:23

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:40:40

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:40:51

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:41:07

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:41:18

### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:41:38

### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:41:48

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:42:08

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:42:18

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:42:40

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:42:51

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:43:10


### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:43:20




### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:43:44

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:43:55

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:44:18

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:44:29

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:44:52

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:45:03

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:45:30

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:45:41

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.DEC.2021 11:46:07

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.DEC.2021 11:46:18

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 2.DEC.2021 11:46:41

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 2.DEC.2021 11:46:52