



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 29.JAN.2021 20:27:05

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 29.JAN.2021 20:27:32

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 29.JAN.2021 20:28:07

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 29.JAN.2021 20:28:37

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 29.JAN.2021 20:29:07

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 29.JAN.2021 20:29:31

Band 2_3 MHz_High_QPSK_RB15#0




Date: 29.JAN.2021 20:30:04

Band 2_3 MHz_High_16QAM_RB15#0




Date: 29.JAN.2021 20:30:26

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 29.JAN.2021 20:30:59

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 29.JAN.2021 20:31:23

Band 2_5 MHz_High_QPSK_RB25#0




Date: 29.JAN.2021 20:31:56

Band 2_5 MHz_High_16QAM_RB25#0




Date: 29.JAN.2021 20:32:26

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 29.JAN.2021 20:33:04

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 29.JAN.2021 20:33:29

Band 2_10 MHz_High_QPSK_RB50#0




Date: 29.JAN.2021 20:34:09

Band 2_10 MHz_High_16QAM_RB50#0




Date: 29.JAN.2021 20:34:37

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 29.JAN.2021 20:35:15

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 29.JAN.2021 20:35:49

Band 2_15 MHz_High_QPSK_RB75#0




Date: 29.JAN.2021 20:36:31

Band 2_15 MHz_High_16QAM_RB75#0




Date: 29.JAN.2021 20:37:01

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 29.JAN.2021 20:37:43

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 29.JAN.2021 20:38:13

Band 2_20 MHz_High_QPSK_RB100#0




Date: 29.JAN.2021 20:38:55

Band 2_20 MHz_High_16QAM_RB100#0




Date: 29.JAN.2021 20:39:27

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 29.JAN.2021 20:39:59

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 29.JAN.2021 20:40:26

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 29.JAN.2021 20:40:58

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 29.JAN.2021 20:41:26

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 29.JAN.2021 20:41:57

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 29.JAN.2021 20:42:23

Band 4_3 MHz_High_QPSK_RB15#0




Date: 29.JAN.2021 20:42:50

Band 4_3 MHz_High_16QAM_RB15#0




Date: 29.JAN.2021 20:43:14

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 29.JAN.2021 20:43:50

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 29.JAN.2021 20:44:15

Band 4_5 MHz_High_QPSK_RB25#0




Date: 29.JAN.2021 20:44:51

Band 4_5 MHz_High_16QAM_RB25#0




Date: 29.JAN.2021 20:45:18

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 29.JAN.2021 20:45:55

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 29.JAN.2021 20:46:23

Band 4_10 MHz_High_QPSK_RB50#0




Date: 29.JAN.2021 20:46:56

Band 4_10 MHz_High_16QAM_RB50#0




Date: 29.JAN.2021 20:47:22

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 29.JAN.2021 20:48:03

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 29.JAN.2021 20:48:37

Band 4_15 MHz_High_QPSK_RB75#0




Date: 29.JAN.2021 20:49:19

Band 4_15 MHz_High_16QAM_RB75#0




Date: 29.JAN.2021 20:49:51

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 29.JAN.2021 20:50:33

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 29.JAN.2021 20:51:04

Band 4_20 MHz_High_QPSK_RB100#0




Date: 29.JAN.2021 20:51:45

Band 4_20 MHz_High_16QAM_RB100#0




Date: 29.JAN.2021 20:52:21

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 29.JAN.2021 20:52:55

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 29.JAN.2021 20:53:19

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 29.JAN.2021 20:53:52

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 29.JAN.2021 20:54:16

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 29.JAN.2021 20:54:47

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 29.JAN.2021 20:55:13

Band 5_3 MHz_High_QPSK_RB15#0




Date: 29.JAN.2021 20:55:48

Band 5_3 MHz_High_16QAM_RB15#0




Date: 29.JAN.2021 20:56:14

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 29.JAN.2021 20:56:45

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 29.JAN.2021 20:57:08

Band 5_5 MHz_High_QPSK_RB25#0




Date: 29.JAN.2021 20:57:42

Band 5_5 MHz_High_16QAM_RB25#0




Date: 29.JAN.2021 20:58:12

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 29.JAN.2021 20:58:44

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 29.JAN.2021 20:59:12

Band 5_10 MHz_High_QPSK_RB50#0




Date: 29.JAN.2021 20:59:44

Band 5_10 MHz_High_16QAM_RB50#0




Date: 29.JAN.2021 21:00:08

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 29.JAN.2021 21:00:41

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 29.JAN.2021 21:01:08

Band 7_5 MHz_High_QPSK_RB25#0




Date: 29.JAN.2021 21:01:41

Band 7_5 MHz_High_16QAM_RB25#0




Date: 29.JAN.2021 21:02:06

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 29.JAN.2021 21:02:40

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 29.JAN.2021 21:03:06

Band 7_10 MHz_High_QPSK_RB50#0




Date: 29.JAN.2021 21:03:43

Band 7_10 MHz_High_16QAM_RB50#0




Date: 29.JAN.2021 21:04:05

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 29.JAN.2021 21:04:43

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 29.JAN.2021 21:05:12

Band 7_15 MHz_High_QPSK_RB75#0




Date: 29.JAN.2021 21:05:51

Band 7_15 MHz_High_16QAM_RB75#0




Date: 29.JAN.2021 21:06:21

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 29.JAN.2021 21:07:00

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 29.JAN.2021 21:07:29

Band 7_20 MHz_High_QPSK_RB100#0




Date: 29.JAN.2021 21:08:00

Band 7_20 MHz_High_16QAM_RB100#0




Date: 29.JAN.2021 21:08:30

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 29.JAN.2021 22:50:53

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 29.JAN.2021 22:51:25

Band 38_5 MHz_High_QPSK_RB25#0




Date: 5.FEB.2021 00:07:50

Band 38_5 MHz_High_16QAM_RB25#0




Date: 29.JAN.2021 22:52:33

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 29.JAN.2021 22:53:11

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 29.JAN.2021 22:53:38

Band 38_10 MHz_High_QPSK_RB50#0




Date: 29.JAN.2021 22:54:12

Band 38_10 MHz_High_16QAM_RB50#0




Date: 29.JAN.2021 22:54:40

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 29.JAN.2021 22:55:21

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 29.JAN.2021 22:56:01

Band 38_15 MHz_High_QPSK_RB75#0




Date: 29.JAN.2021 22:56:46

Band 38_15 MHz_High_16QAM_RB75#0




Date: 29.JAN.2021 22:57:17

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 29.JAN.2021 22:58:02

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 29.JAN.2021 22:58:34

Band 38_20 MHz_High_QPSK_RB100#0



Date: 29.JAN.2021 22:59:19

Band 38_20 MHz_High_16QAM_RB100#0




Date: 29.JAN.2021 22:59:54

Band 40 Lower_5 MHz_High_16QAM_RB25#0



*RBW 100 kHz
*VBW 300 kHz
SWT 10 ms




Date: 3.FEB.2021 23:16:29

Band 40 Lower_5 MHz_High_QPSK_RB25#0




*RBW 100 kHz
*VBW 300 kHz
SWT 10 ms




Date: 3.FEB.2021 23:14:32

Band 40 Lower_5 MHz_Low_16QAM_RB25#0




Date: 3.FEB.2021 23:17:11

Band 40 Lower_5 MHz_Low_QPSK_RB25#0




Date: 3.FEB.2021 23:17:11

Band 40 Lower_10 MHz_16QAM_RB50#0




Date: 3.FEB.2021 23:24:37

Band 40 Lower_10 MHz_QPSK_RB50#0




Date: 3.FEB.2021 23:26:27

Band 40 Upper_5 MHz_Low_16QAM_RB25#0




Date: 3.FEB.2021 23:05:39

Band 40 Upper_5 MHz_Low_QPSK_RB25#0




Date: 3.FEB.2021 23:06:27

Band 40 Upper_5 MHz_High_16QAM_RB25#0




Date: 3.FEB.2021 23:02:46

Band 40 Upper_5 MHz_High_QPSK_RB25#0




Date: 3.FEB.2021 23:01:52

Band 40 Upper_10 MHz_16QAM_RB50#0




Date: 3.FEB.2021 23:08:06

Band 40 Upper_10 MHz_QPSK_RB50#0




Date: 3.FEB.2021 23:07:21

Band 41_QPSK(5.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:27:39

Band 41_QPSK(5.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:30:13

Band 41_16QAM(5.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:28:46

Band 41_16QAM(5.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:29:36

Band 41_QPSK(10.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:36:23

Band 41_QPSK(10.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:33:47

Band 41_16QAM(10.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:35:37

Band 41_16QAM(10.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:34:36

41_QPSK(15.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:42:09

Band 41_QPSK(15.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:40:50

Band 41_16QAM(15.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:43:24

Band 41_16QAM(15.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:40:05

Band 41_QPSK(20.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:44:35

Band 41_QPSK(20.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:47:39

Band 41_16QAM(20.0 MHz, FULL RB) - Left Band Edge




Date: 1.FEB.2021 17:45:28

Band 41_16QAM(20.0 MHz, FULL RB) - Right Band Edge




Date: 1.FEB.2021 17:46:37

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 29.JAN.2021 23:09:42

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 29.JAN.2021 23:10:06

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 29.JAN.2021 23:10:44

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 29.JAN.2021 23:11:16

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 29.JAN.2021 23:11:38

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 29.JAN.2021 23:12:05

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 29.JAN.2021 23:13:30

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 29.JAN.2021 23:13:55

Band 66_5 MHz_High_QPSK_RB25#0




Date: 29.JAN.2021 23:14:31

Band 66_5 MHz_High_16QAM_RB25#0




Date: 29.JAN.2021 23:15:00

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 29.JAN.2021 23:15:27

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 29.JAN.2021 23:15:56

Band 66_10 MHz_High_QPSK_RB50#0




Date: 29.JAN.2021 23:16:36

Band 66_10 MHz_High_16QAM_RB50#0




Date: 29.JAN.2021 23:16:59

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 29.JAN.2021 23:17:26

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 29.JAN.2021 23:17:56

Band 66_15 MHz_High_QPSK_RB75#0




Date: 29.JAN.2021 23:18:41

Band 66_15 MHz_High_16QAM_RB75#0




Date: 29.JAN.2021 23:19:15

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 29.JAN.2021 23:19:44

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 29.JAN.2021 23:20:14

Band 66_20 MHz_High_QPSK_RB100#0



Date: 29.JAN.2021 23:21:00

Band 66_20 MHz_High_16QAM_RB100#0



Date: 29.JAN.2021 23:21:33