

INFINIX MOBILITY LIMITED

Address: FLAT 39 8/F BLOCK D WAH LOK INDUSTRIAL CENTRE 31-35
SHAN MEI STREET FOTAN NT, Hong Kong

Tel: +86-755-61803856

Fax: +86-755-33979211

Email: yiting.luo@transsion.com

Date: 2021-1-28

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road


Columbia, MD 21046

Dear Sir/Madam,

The Main chip, model: MT6785 installed in our product Mobile phone, model: X695, FCC ID: 2AIZN-X695, this chip supports LTE function, but for marketing purpose, this chip only supports LTE band 2/4/5/7/38/40/41/66, not support other LTE bands. The other LTE bands was disabled to use by manufacture in the software, the end user has no capability to activate it.

The RF chip, model MT6631, which installed in our product Mobile phone, model: X695, FCC ID: 2AIZN-X695, supports 2.4G Wi-Fi, 5G Wi-Fi, BT, GPS and FM function, but for marketing purpose, this chip only supports 2.4G Wi-Fi, 5G Wi-Fi(5150-5250 MHz; 5725-5850 MHz), BT, GPS and FM function. The 5G Wi-Fi(5250-5350 MHz; 5470-5725 MHz) was disabled to use by manufacture in the software, the end user has no capability to activate it.

Signature:



Yiting Luo
Project Manager