



Please refer to following plots:




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 21:22:15




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 21:22:31

Band 2_3 MHz_Middle_QPSK_RB15#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:25:49

Band 2_3 MHz_Middle_16QAM_RB15#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:26:02


Band 2_5 MHz_Middle_QPSK_RB25#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai

Date: 26.MAY.2024 21:28:24


Band 2_5 MHz_Middle_16QAM_RB25#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai


Date: 26.MAY.2024 21:28:41

Band 2_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:33:35

Band 2_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:33:51

Band 2_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:36:59

Band 2_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:37:16

Band 2_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 21:40:03

Band 2_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 21:40:20

Band 4_1.4 MHz_Middle_QPSK_RB6#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:45:55

Band 4_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:46:08

Band 4_3 MHz_Middle_QPSK_RB15#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:52:35

Band 4_3 MHz_Middle_16QAM_RB15#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 21:52:51


Band 4_5 MHz_Middle_QPSK_RB25#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai

Date: 26.MAY.2024 21:59:50


Band 4_5 MHz_Middle_16QAM_RB25#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai


Date: 26.MAY.2024 22:00:07

Band 4_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:05:26

Band 4_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:05:39

Band 4_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:08:20

Band 4_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:08:33

Band 4_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:11:02

Band 4_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:11:19

Band 7_5 MHz_Middle_QPSK_RB25#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:12:46

Band 7_5 MHz_Middle_16QAM_RB25#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:13:02

Band 7_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:17:36

Band 7_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:17:52

Band 7_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:22:40

Band 7_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:22:54

Band 7_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:26:49

Band 7_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:27:06

Band 38_5 MHz_Middle_QPSK_RB25#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:28:53

Band 38_5 MHz_Middle_16QAM_RB25#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
 Date: 26.MAY.2024 22:29:09

Band 38_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:31:14

Band 38_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:31:27

Band 38_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:36:40

Band 38_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:37:00

Band 38_20 MHz_Middle_QPSK_RB100#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:44:35

Band 38_20 MHz_Middle_16QAM_RB100#0



ProjectNo.:2401S54552E-RF Tester:Allen Bai
Date: 26.MAY.2024 22:44:54