

OBDSTAR Technology Co., Ltd

19th floor, Building T1, Hi Park, LuoZu Community, Shiyuan Street, Baoan District,
Shenzhen, Guangdong, China

Date: December 11, 2023

FCC ID: 2AJ2D-DP550

Model Number: DP55, Codify Monster 501, DiagMate, KeyExpert, MT500, MT501, DashMate, DashExpert, Doctor M500, MK5, Motor Master 5, MD005, Expert MDT 5, PowerDiag MS500, Motorcycle5, SpeedPrime, SpeedExplorer, Motor Scanner 501, IM50, IM50 Pro, IM50 Lite, KP50, KP50 Pro, KP50 Lite, X300M Pro, X500M, X500M Pro, ODO Elite, Moto 100, Moto 100 Air, Moto Air, Moto Air 2, MS50 Air, iMoto, iScan, MD50 PRO, GD Master, GD Pro4, CRS100, CRS100 Pro, CRS Air, CRS PAD, TruckExpert, TE50 Motor Scanner 5, Eagle, Eagle 2, Falcon, Falcon 2, DScan, DScan Pro, Dscan ELite, DS50, DS50 Pro, DS500, DS500 Pro, Diesel Master, DM50, DM50 Pro

To: Federal Communication Commission


Authorization and Evaluation Division 7435 Oakland Mills Road
Columbia, MD 21048

To Whom It May Concern,

We, OBDSTAR Technology Co., Ltd hereby declare that our product (Diagnostic Tool) Model Number: DP55, Codify Monster 501, DiagMate, KeyExpert, MT500, MT501, DashMate, DashExpert, Doctor M500, MK5, Motor Master 5, MD005, Expert MDT 5, PowerDiag MS500, Motorcycle5, SpeedPrime, SpeedExplorer, Motor Scanner 501, IM50, IM50 Pro, IM50 Lite, KP50, KP50 Pro, KP50 Lite, X300M Pro, X500M, X500M Pro, ODO Elite, Moto 100, Moto 100 Air, Moto Air, Moto Air 2, MS50 Air, iMoto, iScan, MD50 PRO, GD Master, GD Pro4, CRS100, CRS100 Pro, CRS Air, CRS PAD, TruckExpert, TE50 Motor Scanner 5, Eagle, Eagle 2, Falcon, Falcon 2, DScan, DScan Pro, Dscan ELite, DS50, DS50 Pro, DS500, DS500 Pro, Diesel Master, DM50, DM50 Pro board, Schematic, Hardware version, Software version, structure and internal photos are same, named and appearance differently due to marketing purposes.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely,



(Signed)

Name/Title: Hongtao Wang / Manager

Company: OBDSTAR Technology Co., Ltd

Address: 19th floor, Building T1, Hi Park, LuoZu Community, Shiyuan Street, Baoan

OBDSTAR Technology Co., Ltd

*19th floor, Building T1, Hi Park, Luoazu Community, Shiyan Street, Baoan District,
Shenzhen, Guangdong, China*

District, Shenzhen, Guangdong, China

Tel: +86-755-86702171

Fax: +86-755-86707161

E-Mail: xycd@obdstar.cn