



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 7.JAN.2023 12:00:15

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 7.JAN.2023 12:00:21

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 7.JAN.2023 12:00:30

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 7.JAN.2023 12:00:37

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 7.JAN.2023 12:00:46

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 7.JAN.2023 12:00:53

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 7.JAN.2023 12:01:01

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 7.JAN.2023 12:01:09

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 7.JAN.2023 12:01:18

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 7.JAN.2023 12:01:26

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 7.JAN.2023 12:01:34

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 7.JAN.2023 12:01:43

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 7.JAN.2023 12:01:53

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 7.JAN.2023 12:02:02

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 7.JAN.2023 12:02:11


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 7.JAN.2023 12:02:20




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 7.JAN.2023 12:02:30

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 7.JAN.2023 12:02:37

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 7.JAN.2023 12:02:46

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 7.JAN.2023 12:02:53

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 7.JAN.2023 12:03:03

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 7.JAN.2023 12:03:11

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 7.JAN.2023 12:03:20

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 7.JAN.2023 12:03:27

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 7.JAN.2023 12:03:38

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 7.JAN.2023 12:03:46

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 7.JAN.2023 12:03:53

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 7.JAN.2023 12:04:00

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 7.JAN.2023 12:04:09

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 7.JAN.2023 12:04:17

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 7.JAN.2023 12:04:25


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 7.JAN.2023 12:04:31




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 7.JAN.2023 12:04:41

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 7.JAN.2023 12:04:49

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 7.JAN.2023 12:04:58

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 7.JAN.2023 12:05:05

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 7.JAN.2023 12:05:16

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 7.JAN.2023 12:05:25

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 7.JAN.2023 12:05:34

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 7.JAN.2023 12:05:42

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 7.JAN.2023 12:05:52

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 7.JAN.2023 12:05:59

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 7.JAN.2023 12:06:07

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 7.JAN.2023 12:06:15

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 7.JAN.2023 12:06:25

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 7.JAN.2023 12:06:33

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 7.JAN.2023 12:06:41


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 7.JAN.2023 12:06:49




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 9.JAN.2023 13:28:09

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 9.JAN.2023 13:28:42

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 9.JAN.2023 13:29:29

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 9.JAN.2023 13:29:49

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 9.JAN.2023 13:30:27

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 9.JAN.2023 13:30:46

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 9.JAN.2023 13:31:28

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 9.JAN.2023 13:32:04

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 9.JAN.2023 13:32:43

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 9.JAN.2023 13:33:03

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 9.JAN.2023 13:33:46

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 9.JAN.2023 13:34:05

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 9.JAN.2023 13:34:45

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 9.JAN.2023 13:35:04

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 9.JAN.2023 13:35:35


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 9.JAN.2023 13:35:57




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 7.JAN.2023 16:35:57

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 7.JAN.2023 16:36:04

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 7.JAN.2023 16:36:11

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 7.JAN.2023 16:36:18

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 7.JAN.2023 16:36:27

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 7.JAN.2023 16:36:34

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 7.JAN.2023 16:36:42

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 7.JAN.2023 16:36:50

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 7.JAN.2023 16:36:59

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 7.JAN.2023 16:37:07

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 7.JAN.2023 16:37:15

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 7.JAN.2023 16:37:23

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 7.JAN.2023 16:37:33

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 7.JAN.2023 16:37:42

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 7.JAN.2023 16:37:52


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 7.JAN.2023 16:38:01




### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 7.JAN.2023 16:39:04

### Band 12\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 7.JAN.2023 16:39:12

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 7.JAN.2023 16:39:19

### Band 12\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 7.JAN.2023 16:39:26

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0




Date: 7.JAN.2023 16:39:36

### Band 12\_3 MHz\_Low\_16QAM\_RB15#0




Date: 7.JAN.2023 16:39:44

### Band 12\_3 MHz\_High\_QPSK\_RB15#0




Date: 7.JAN.2023 16:39:51

### Band 12\_3 MHz\_High\_16QAM\_RB15#0




Date: 7.JAN.2023 16:39:58

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0




Date: 7.JAN.2023 16:40:08

### Band 12\_5 MHz\_Low\_16QAM\_RB25#0




Date: 7.JAN.2023 16:40:17

### Band 12\_5 MHz\_High\_QPSK\_RB25#0




Date: 7.JAN.2023 16:40:24

### Band 12\_5 MHz\_High\_16QAM\_RB25#0




Date: 7.JAN.2023 16:40:32

### Band 12\_10 MHz\_Low\_QPSK\_RB50#0




Date: 7.JAN.2023 16:40:43

### Band 12\_10 MHz\_Low\_16QAM\_RB50#0




Date: 7.JAN.2023 16:40:52

### Band 12\_10 MHz\_High\_QPSK\_RB50#0



Date: 7.JAN.2023 16:41:01


### Band 12\_10 MHz\_High\_16QAM\_RB50#0



Date: 7.JAN.2023 16:41:09




### Band 13\_5 MHz\_Low\_QPSK\_RB25#0




Date: 7.JAN.2023 16:41:19

### Band 13\_5 MHz\_Low\_16QAM\_RB25#0




Date: 7.JAN.2023 16:41:26

### Band 13\_5 MHz\_High\_QPSK\_RB25#0




Date: 7.JAN.2023 16:41:35

### Band 13\_5 MHz\_High\_16QAM\_RB25#0




Date: 7.JAN.2023 16:41:43

### Band 13\_10 MHz\_Low\_QPSK\_RB50#0




Date: 9.JAN.2023 17:20:50

### Band 13\_10 MHz\_Low\_16QAM\_RB50#0




Date: 9.JAN.2023 17:22:03

### Band 13\_10 MHz\_High\_QPSK\_RB50#0




Date: 9.JAN.2023 17:22:40

### Band 13\_10 MHz\_High\_16QAM\_RB50#0




Date: 9.JAN.2023 17:22:57

### Band 17\_5 MHz\_Low\_QPSK\_RB25#0




Date: 7.JAN.2023 16:43:24

### Band 17\_5 MHz\_Low\_16QAM\_RB25#0




Date: 7.JAN.2023 16:43:33

### Band 17\_5 MHz\_High\_QPSK\_RB25#0




Date: 7.JAN.2023 16:43:41

### Band 17\_5 MHz\_High\_16QAM\_RB25#0




Date: 7.JAN.2023 16:43:48

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0




Date: 7.JAN.2023 16:43:59

### Band 17\_10 MHz\_Low\_16QAM\_RB50#0




Date: 7.JAN.2023 16:44:08

### Band 17\_10 MHz\_High\_QPSK\_RB50#0



Date: 7.JAN.2023 16:44:17


### Band 17\_10 MHz\_High\_16QAM\_RB50#0



Date: 7.JAN.2023 16:44:25




### Band 26\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 10.JAN.2023 09:18:19

### Band 26\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 10.JAN.2023 09:18:42

### Band 26\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 10.JAN.2023 09:24:42

### Band 26\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 10.JAN.2023 09:25:03

### Band 26\_3 MHz\_Low\_QPSK\_RB15#0




Date: 10.JAN.2023 09:25:47

### Band 26\_3 MHz\_Low\_16QAM\_RB15#0




Date: 10.JAN.2023 09:26:05

### Band 26\_3 MHz\_High\_QPSK\_RB15#0




Date: 10.JAN.2023 09:26:46

### Band 26\_3 MHz\_High\_16QAM\_RB15#0




Date: 10.JAN.2023 09:27:06

### Band 26\_5 MHz\_Low\_QPSK\_RB25#0




Date: 10.JAN.2023 09:27:45

### Band 26\_5 MHz\_Low\_16QAM\_RB25#0




Date: 10.JAN.2023 09:28:03

### Band 26\_5 MHz\_High\_QPSK\_RB25#0




Date: 10.JAN.2023 09:28:56

### Band 26\_5 MHz\_High\_16QAM\_RB25#0




Date: 10.JAN.2023 09:29:13

### Band 26\_10 MHz\_QPSK\_RB50#0




Date: 10.JAN.2023 09:30:15

### Band 26\_10 MHz\_16QAM\_RB50#0




Date: 10.JAN.2023 09:30:36

### Band 26\_15 MHz\_Low\_QPSK\_RB75#0



Date: 10.JAN.2023 10:07:52


### Band 26\_15 MHz\_Low\_16QAM\_RB75#0



Date: 10.JAN.2023 10:08:00




### Band 26\_15 MHz\_High\_QPSK\_RB75#0




Date: 10.JAN.2023 10:08:08

### Band 26\_15 MHz\_High\_16QAM\_RB75#0




Date: 10.JAN.2023 10:08:16

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 9.JAN.2023 13:07:31

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 9.JAN.2023 13:09:23

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 9.JAN.2023 13:10:13

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 9.JAN.2023 13:10:34

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 9.JAN.2023 13:11:19

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 9.JAN.2023 13:11:36

### Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 9.JAN.2023 13:12:04

### Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 9.JAN.2023 13:12:23

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 9.JAN.2023 13:20:03

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 9.JAN.2023 13:19:43

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 9.JAN.2023 13:13:55

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 9.JAN.2023 13:14:16

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0



Date: 9.JAN.2023 13:24:08


### Band 38\_20 MHz\_Low\_16QAM\_RB100#0



Date: 9.JAN.2023 13:24:27




### Band 38\_20 MHz\_High\_QPSK\_RB100#0




Date: 9.JAN.2023 13:23:29

### Band 38\_20 MHz\_High\_16QAM\_RB100#0




Date: 9.JAN.2023 13:22:09

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 9.JAN.2023 11:50:07

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 9.JAN.2023 11:50:28

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 9.JAN.2023 11:50:58

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 9.JAN.2023 11:51:19

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 9.JAN.2023 11:56:10

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 9.JAN.2023 11:56:30

### Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 9.JAN.2023 11:55:40

### Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 9.JAN.2023 11:55:13

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 9.JAN.2023 11:57:35

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 9.JAN.2023 11:57:51

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 9.JAN.2023 11:58:35

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 9.JAN.2023 11:58:54

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0



Date: 9.JAN.2023 12:00:20


### Band 41\_20 MHz\_Low\_16QAM\_RB100#0



Date: 9.JAN.2023 12:00:35




### Band 41\_20 MHz\_High\_QPSK\_RB100#0




Date: 9.JAN.2023 12:01:08

### Band 41\_20 MHz\_High\_16QAM\_RB100#0




Date: 9.JAN.2023 12:01:27

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 9.JAN.2023 09:41:30

### Band 66\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 9.JAN.2023 09:41:38

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 9.JAN.2023 09:41:46

### Band 66\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 9.JAN.2023 09:41:53

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0




Date: 9.JAN.2023 09:42:03

### Band 66\_3 MHz\_Low\_16QAM\_RB15#0




Date: 9.JAN.2023 09:42:11

### Band 66\_3 MHz\_High\_QPSK\_RB15#0




Date: 9.JAN.2023 09:42:19

### Band 66\_3 MHz\_High\_16QAM\_RB15#0




Date: 9.JAN.2023 09:42:26

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0




Date: 9.JAN.2023 09:42:37

### Band 66\_5 MHz\_Low\_16QAM\_RB25#0




Date: 9.JAN.2023 09:42:45

### Band 66\_5 MHz\_High\_QPSK\_RB25#0




Date: 9.JAN.2023 09:42:54

### Band 66\_5 MHz\_High\_16QAM\_RB25#0




Date: 9.JAN.2023 09:43:02

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0



Date: 9.JAN.2023 09:43:13


### Band 66\_10 MHz\_Low\_16QAM\_RB50#0



Date: 9.JAN.2023 09:43:22




### Band 66\_10 MHz\_High\_QPSK\_RB50#0




Date: 9.JAN.2023 09:43:31

### Band 66\_10 MHz\_High\_16QAM\_RB50#0




Date: 9.JAN.2023 09:43:40

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0




Date: 9.JAN.2023 09:43:50

### Band 66\_15 MHz\_Low\_16QAM\_RB75#0




Date: 9.JAN.2023 09:43:58

### Band 66\_15 MHz\_High\_QPSK\_RB75#0




Date: 9.JAN.2023 09:44:06

### Band 66\_15 MHz\_High\_16QAM\_RB75#0




Date: 9.JAN.2023 09:44:13

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0




Date: 9.JAN.2023 09:44:24

### Band 66\_20 MHz\_Low\_16QAM\_RB100#0




Date: 9.JAN.2023 09:44:31

### Band 66\_20 MHz\_High\_QPSK\_RB100#0



Date: 9.JAN.2023 09:44:40

### Band 66\_20 MHz\_High\_16QAM\_RB100#0



Date: 9.JAN.2023 09:44:48