



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 15.NOV.2022 15:55:16

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 15.NOV.2022 15:55:35

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 15.NOV.2022 15:55:54

### Band 2\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 15.NOV.2022 15:56:15

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 15.NOV.2022 15:56:34

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 15.NOV.2022 15:56:52

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 15.NOV.2022 15:57:09

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 15.NOV.2022 15:57:27

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 15.NOV.2022 15:57:43

### Band 2\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 15.NOV.2022 15:57:58

Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 15.NOV.2022 15:58:17

Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 15.NOV.2022 15:58:32

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.NOV.2022 15:58:52

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.NOV.2022 15:59:11

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 15.NOV.2022 15:59:30


### Band 2\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 15.NOV.2022 15:59:50




### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.NOV.2022 16:00:09

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.NOV.2022 16:00:31

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.NOV.2022 16:00:52

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.NOV.2022 16:01:12

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 15.NOV.2022 16:01:31

### Band 2\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 15.NOV.2022 16:01:51

### Band 2\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.NOV.2022 16:02:11

### Band 2\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.NOV.2022 16:02:30

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.NOV.2022 16:02:54

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.NOV.2022 16:03:16

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 15.NOV.2022 16:03:42

Band 2\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 15.NOV.2022 16:04:04

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.NOV.2022 16:04:26

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.NOV.2022 16:04:48

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0



Date: 15.NOV.2022 16:05:12


### Band 2\_20 MHz\_Low\_16QAM\_RB100#0



Date: 15.NOV.2022 16:05:35




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 15.NOV.2022 16:05:58

### Band 2\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 15.NOV.2022 16:06:20

Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 15.NOV.2022 16:06:43

Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 15.NOV.2022 16:07:06

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 15.NOV.2022 16:07:24

Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 15.NOV.2022 16:07:42

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 15.NOV.2022 16:08:00

### Band 4\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 15.NOV.2022 16:08:18

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 15.NOV.2022 16:08:37

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 15.NOV.2022 16:08:52

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 15.NOV.2022 16:09:11

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 15.NOV.2022 16:09:30

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 15.NOV.2022 16:09:48

Band 4\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 15.NOV.2022 16:10:03

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 15.NOV.2022 16:10:19


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 15.NOV.2022 16:10:34




Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.NOV.2022 16:10:55

Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.NOV.2022 16:11:14

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 15.NOV.2022 16:11:36

### Band 4\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 15.NOV.2022 16:12:01

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.NOV.2022 16:12:21

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.NOV.2022 16:12:39

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.NOV.2022 16:13:00

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.NOV.2022 16:13:20

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 15.NOV.2022 16:13:40

### Band 4\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 15.NOV.2022 16:13:59

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.NOV.2022 16:14:19

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.NOV.2022 16:14:36

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.NOV.2022 16:15:00

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.NOV.2022 16:15:22

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0



Date: 15.NOV.2022 16:15:48


Band 4\_15 MHz\_Middle\_16QAM\_RB75#0



Date: 15.NOV.2022 16:16:16




### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.NOV.2022 16:16:42

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.NOV.2022 16:17:04

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.NOV.2022 16:17:28

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.NOV.2022 16:17:51

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 15.NOV.2022 16:18:14

### Band 4\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 15.NOV.2022 16:18:39

### Band 4\_20 MHz\_High\_QPSK\_RB100#0




Date: 15.NOV.2022 16:19:02

### Band 4\_20 MHz\_High\_16QAM\_RB100#0




Date: 15.NOV.2022 16:19:25

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.NOV.2022 16:19:43

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.NOV.2022 16:20:02

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 15.NOV.2022 16:20:18

### Band 7\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 15.NOV.2022 16:20:33

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.NOV.2022 16:20:53

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.NOV.2022 16:21:12

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0



Date: 15.NOV.2022 16:21:33


### Band 7\_10 MHz\_Low\_16QAM\_RB50#0



Date: 15.NOV.2022 16:21:52




Band 7\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 15.NOV.2022 16:22:12

Band 7\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 15.NOV.2022 16:22:32

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.NOV.2022 16:22:52

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.NOV.2022 16:23:11

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.NOV.2022 16:23:35

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.NOV.2022 16:23:57

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 15.NOV.2022 16:24:19

### Band 7\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 15.NOV.2022 16:24:41

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.NOV.2022 16:25:04

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.NOV.2022 16:25:26

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.NOV.2022 16:25:50

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.NOV.2022 16:26:13

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 15.NOV.2022 16:26:36

### Band 7\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 15.NOV.2022 16:26:58

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 15.NOV.2022 16:27:22


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 15.NOV.2022 16:27:44




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.NOV.2022 10:57:00

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.NOV.2022 10:57:14

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 2.NOV.2022 10:57:29

### Band 5\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 2.NOV.2022 10:57:43

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.NOV.2022 10:58:00

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.NOV.2022 11:00:58

Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.NOV.2022 11:01:17

Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.NOV.2022 11:01:31

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 2.NOV.2022 11:01:46

### Band 5\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 2.NOV.2022 11:02:00

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.NOV.2022 11:02:14

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.NOV.2022 11:02:28

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.NOV.2022 11:02:45

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.NOV.2022 11:02:59

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 2.NOV.2022 11:03:18


### Band 5\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 2.NOV.2022 11:03:35




Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.NOV.2022 11:03:54

Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.NOV.2022 11:04:11

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.NOV.2022 11:04:32

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.NOV.2022 11:04:50

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 2.NOV.2022 11:05:09

### Band 5\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 2.NOV.2022 11:05:27

### Band 5\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.NOV.2022 11:05:46

### Band 5\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.NOV.2022 11:06:05

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.NOV.2022 11:06:22

Band 12\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.NOV.2022 11:06:36

### Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 2.NOV.2022 11:07:50

### Band 12\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 2.NOV.2022 11:08:07

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.NOV.2022 11:08:21

### Band 12\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.NOV.2022 11:08:38

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0



Date: 2.NOV.2022 11:08:54


### Band 12\_3 MHz\_Low\_16QAM\_RB15#0



Date: 2.NOV.2022 11:09:12




### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 2.NOV.2022 11:09:26

### Band 12\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 2.NOV.2022 11:09:40

### Band 12\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.NOV.2022 11:09:55

### Band 12\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.NOV.2022 11:10:09

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.NOV.2022 11:10:28

### Band 12\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.NOV.2022 11:10:46

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 2.NOV.2022 11:11:05

### Band 12\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 2.NOV.2022 11:11:22

### Band 12\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.NOV.2022 11:11:38

### Band 12\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.NOV.2022 11:11:55

### Band 12\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.NOV.2022 11:12:16

### Band 12\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.NOV.2022 11:12:37

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 2.NOV.2022 11:12:56

Band 12\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 2.NOV.2022 11:13:15

### Band 12\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.NOV.2022 11:13:34


### Band 12\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.NOV.2022 11:13:49




### Band 17\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.NOV.2022 11:14:13

### Band 17\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.NOV.2022 11:14:34

### Band 17\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 2.NOV.2022 11:14:52

### Band 17\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 2.NOV.2022 11:15:10

### Band 17\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.NOV.2022 11:16:52

### Band 17\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.NOV.2022 11:17:10

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.NOV.2022 11:17:27

### Band 17\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.NOV.2022 11:17:42

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 2.NOV.2022 11:18:01

### Band 17\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 2.NOV.2022 11:18:17

### Band 17\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.NOV.2022 11:18:33

### Band 17\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.NOV.2022 11:18:51

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.NOV.2022 14:33:59

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.NOV.2022 14:34:26

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 2.NOV.2022 14:34:47


### Band 38\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 2.NOV.2022 14:35:07




### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.NOV.2022 14:35:34

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.NOV.2022 14:35:57

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.NOV.2022 14:36:15

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.NOV.2022 14:36:32

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0



Date: 2.NOV.2022 14:36:53


### Band 38\_10 MHz\_Middle\_16QAM\_RB50#0



Date: 2.NOV.2022 14:37:13




### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.NOV.2022 14:38:10

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.NOV.2022 14:38:28

### Band 38\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 2.NOV.2022 14:38:50

### Band 38\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 2.NOV.2022 14:39:07

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.NOV.2022 14:39:29

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.NOV.2022 14:39:50

Band 38\_20 MHz\_Low\_QPSK\_RB100#0



Date: 2.NOV.2022 14:40:10


Band 38\_20 MHz\_Low\_16QAM\_RB100#0



Date: 2.NOV.2022 14:40:28




### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 2.NOV.2022 14:40:46

### Band 38\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 2.NOV.2022 14:41:04

### Band 38\_20 MHz\_High\_QPSK\_RB100#0




Date: 2.NOV.2022 14:41:23

### Band 38\_20 MHz\_High\_16QAM\_RB100#0




Date: 2.NOV.2022 14:41:40

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.NOV.2022 15:15:23

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.NOV.2022 15:15:47

### Band 41\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 2.NOV.2022 15:16:05

### Band 41\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 2.NOV.2022 15:16:32

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.NOV.2022 15:16:54

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.NOV.2022 15:17:18

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.NOV.2022 15:18:27

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.NOV.2022 15:18:49

### Band 41\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 2.NOV.2022 15:19:08

### Band 41\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 2.NOV.2022 15:19:26

### Band 41\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.NOV.2022 15:19:45


### Band 41\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.NOV.2022 15:20:03




### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.NOV.2022 15:21:17

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.NOV.2022 15:21:38

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 2.NOV.2022 15:22:02

Band 41\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 2.NOV.2022 15:22:23

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.NOV.2022 15:22:48

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.NOV.2022 15:23:12

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.NOV.2022 15:24:13

### Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.NOV.2022 15:24:35

### Band 41\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 2.NOV.2022 15:24:58

### Band 41\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 2.NOV.2022 15:25:19

Band 41\_20 MHz\_High\_QPSK\_RB100#0




Date: 2.NOV.2022 15:25:44

Band 41\_20 MHz\_High\_16QAM\_RB100#0




Date: 2.NOV.2022 15:26:06

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 15.NOV.2022 17:45:07

### Band 66\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 15.NOV.2022 17:45:22

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0



Date: 15.NOV.2022 17:46:32


### Band 66\_1.4 MHz\_Middle\_16QAM\_RB6#0



Date: 15.NOV.2022 17:46:51




### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 15.NOV.2022 17:47:06

### Band 66\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 15.NOV.2022 17:47:25

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0



Date: 15.NOV.2022 17:47:43


### Band 66\_3 MHz\_Low\_16QAM\_RB15#0



Date: 15.NOV.2022 17:47:58




### Band 66\_3 MHz\_High\_QPSK\_RB15#0




Date: 15.NOV.2022 17:48:49

### Band 66\_3 MHz\_High\_16QAM\_RB15#0




Date: 15.NOV.2022 17:49:07

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.NOV.2022 17:49:29

### Band 66\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.NOV.2022 17:49:48

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 15.NOV.2022 17:50:08

### Band 66\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 15.NOV.2022 17:50:27

### Band 66\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.NOV.2022 17:50:46

### Band 66\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.NOV.2022 17:51:05

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0



Date: 15.NOV.2022 17:51:28


### Band 66\_10 MHz\_Low\_16QAM\_RB50#0



Date: 15.NOV.2022 17:51:44




### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 15.NOV.2022 17:52:01

### Band 66\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 15.NOV.2022 17:52:18

### Band 66\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.NOV.2022 17:52:38

### Band 66\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.NOV.2022 17:52:58

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.NOV.2022 17:53:23

### Band 66\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.NOV.2022 17:53:45

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 15.NOV.2022 17:54:08

### Band 66\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 15.NOV.2022 17:54:30

### Band 66\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.NOV.2022 17:54:53

### Band 66\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.NOV.2022 17:55:13

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.NOV.2022 17:55:35

### Band 66\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.NOV.2022 17:55:55

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 15.NOV.2022 17:56:18

### Band 66\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 15.NOV.2022 17:56:41

### Band 66\_20 MHz\_High\_QPSK\_RB100#0



Date: 15.NOV.2022 17:57:04

### Band 66\_20 MHz\_High\_16QAM\_RB100#0



Date: 15.NOV.2022 17:57:27