



Please refer to following plots:




Date: 15.NOV.2022 16:44:49




Date: 18.NOV.2022 10:52:00

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:46:40

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:46:51

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:47:05

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:47:16

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:47:33

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:47:44

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:47:58

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:48:09

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:48:24

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:48:35

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:48:53

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:49:04

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:49:22

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:49:33

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:49:51

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:50:02

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:50:23

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:50:34

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:50:53

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:51:04

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:51:19

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:51:30

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:51:51

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:52:02

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:52:20

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:52:31

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:52:53

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:53:04

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:53:25

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:53:36

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:53:58

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:54:09

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:54:28

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:54:39

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:55:01

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.NOV.2022 10:59:46

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:55:26

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:00:38

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:55:52

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:01:58

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:56:23

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:04:37

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:56:48

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:05:31

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:57:14

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:06:35

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:57:43

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:07:17

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:58:09

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:07:56

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:58:38

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.NOV.2022 11:09:01

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:59:07

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:59:18

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 16:59:37

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 16:59:48

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:00:04

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:00:15

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:00:36

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:00:47

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:01:08

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:01:19

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:01:40

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:01:52

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:02:12

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:02:24

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:02:42

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:02:53

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:03:12

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 17:03:23

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:03:42

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:03:54

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:04:12

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:04:23

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:04:41

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:04:52

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:05:13

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:05:24

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:05:43

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:05:54

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:06:10

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:06:21

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:06:44

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:06:56

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:07:14

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:07:25

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:07:43

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:07:54

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:08:18

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:08:30

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:08:48

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:08:59

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 17:09:18

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 15.NOV.2022 17:09:29

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:44:47

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:44:57

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:45:10

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:45:20

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:45:32

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:45:43

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:45:57

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:46:07

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:46:23

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:46:33

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:46:46

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:46:56

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:47:10

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:47:20

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:47:33

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:47:43

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:47:56

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:48:06

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:48:20

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:48:31

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:48:47

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:48:57

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:49:10

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:49:21

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:50:36

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:50:46

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(30MHz-1GHz)




Date: 18.NOV.2022 11:18:09

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:51:09

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.NOV.2022 11:21:26

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:52:28

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:52:44

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:52:55

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:53:07

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:53:18

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:54:58

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:55:08

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:55:24

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:55:34

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:55:47

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:55:57

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:56:10

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:56:20

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:56:34

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:56:44

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:57:00

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:57:11

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:57:24

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:57:34

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:57:53

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:58:03

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:58:16

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:58:26

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:58:42

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:58:52

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:59:06

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:59:16

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:59:29

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 13:59:40

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 13:59:52

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.NOV.2022 14:00:03

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:44:40

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:38:25

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:45:03

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:38:58

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:45:26

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:40:18

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:45:51

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:41:00

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:46:18

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:41:52

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:46:41

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:42:42

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:47:06

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 14:47:16

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:47:30

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 14:47:40

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:47:57

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:43:40

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:48:22

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 14:48:32

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:48:46

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 14:48:56

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.NOV.2022 14:49:13

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 14:49:23

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:26:46

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:30:13

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:27:09

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:32:08

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:27:36

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:32:46

Band 41_5 MHz_High_QPSK_RB25#0_2(26.5GHz-27GHz)




Date: 23.NOV.2022 17:10:09

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:28:38

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:33:15

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:29:01

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:33:49

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:29:25

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:34:48

Band 41_10 MHz_High_QPSK_RB50#0_2(26.5GHz-27GHz)




Date: 23.NOV.2022 17:15:18

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:30:37

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 18.NOV.2022 13:37:00

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:31:01

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 15:31:11

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:31:28

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 15:31:38

Band 41_15 MHz_High_QPSK_RB75#0_2(26.5GHz-27GHz)




Date: 23.NOV.2022 17:18:45

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:32:33

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 15:32:43

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:32:57

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 15:33:07

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.NOV.2022 15:33:24

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.NOV.2022 15:33:34

Band 41_20 MHz_High_QPSK_RB100#0_2(26.5GHz-27GHz)




Date: 23.NOV.2022 17:20:52

Band 66_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:00:51

Band 66_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:02:15

Band 66_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:02:33

Band 66_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:02:44

Band 66_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:02:58

Band 66_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:03:10

Band 66_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:03:30

Band 66_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:03:41

Band 66_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:03:55

Band 66_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:04:06

Band 66_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:04:24

Band 66_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:04:35

Band 66_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:04:52

Band 66_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:05:03

Band 66_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:05:18

Band 66_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:05:29

Band 66_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:05:44

Band 66_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:05:55

Band 66_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:06:13

Band 66_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:06:25

Band 66_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:06:43

Band 66_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:06:54

Band 66_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:07:13

Band 66_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:07:24

Band 66_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:07:45

Band 66_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:07:56

Band 66_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:08:14

Band 66_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:08:25

Band 66_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:08:43

Band 66_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:08:54

Band 66_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:09:16

Band 66_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:09:27

Band 66_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 15.NOV.2022 18:09:48

Band 66_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 15.NOV.2022 18:09:59

Band 66_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 15.NOV.2022 18:10:18

Band 66_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)



Date: 15.NOV.2022 18:10:29