

SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SEWA2309000114RG02

Rev.: 01 Page: 64 of 64

Frequency Error VS. Temperature

Temperature										
Band	scs	Bandwidth	Modulation	Channel	RB Config	Voltag e	Temperatur e	Deviation (Hz)	Deviation (ppm)	Verdic t
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	-30	-1.500000	-0.001793	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	-20	3.200000	0.003825	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	-10	3.400000	0.004065	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	0	2.200000	0.002630	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	10	1.400000	0.001674	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	20	2.000000	0.002391	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	30	6.300000	0.007531	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	40	0.400000	0.000478	PASS
N26-824-849	15	20	DFT- PI2BPSK	М	Outer_Full	NV	50	1.700000	0.002032	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	-30	4.000000	0.004782	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	-20	7.300000	0.008727	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	-10	5.700000	0.006814	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	0	4.600000	0.005499	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	10	11.60000 0	0.013867	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	20	6.200000	0.007412	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	30	5.800000	0.006934	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	40	7.800000	0.009325	PASS
N26-824-849	15	20	CP-QPSK	М	Outer_Full	NV	50	1.200000	0.001435	PASS

---End of Attachment---



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company, Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443,

South of No. 6 Plant, No. 1, Runsheng Road, Suzhou Industrial Park, Suzhou Area, China (Jiangsu) Pilot Free Trade Zone 中国 - 苏州 - 中国(江苏)自由贸易试验区苏州片区苏州工业园区海胜路1号的6号厂房南部 邮编: 215000 t (86–512) 62992980 www.sgsgroup.com.cn t (86–512) 62992980 sgs.china@sgs.com