

HMD Global Oy
Karaportti 2 02610 Espoo, FINLAND

Date: May 17, 2018

We, HMD Global Oy, declare on our sole responsibility for the product of TA-1049,TA-1074;TA-1063, TA-1057 (model name) as below:

SKU1 include: TA-1063; TA-1057

SKU2 include: TA-1049; TA-1074

SKU1 and SKU2 are different in supporting bands. SKU2 supported bands are cover SKU1 supported bands.

The software difference between SKU2 and SKU1:

- ◆ Disable not support bands on SKU1 from SKU2. SKU1 disable LTE bands 2,4,12,17,28,WCDMA bands 2,4,
- ◆ Disable not support bands on SKU2 from SKU1, SKU2 disable LTE band 20.
- ◆ Others bands are same as SKU2. All the others software functions are the same.


The Hardware difference between SKU2 and SKU1:

- ◆ Remove all of components which to be related not support bands on SKU1 and SKU2. All the others HW components are the same.
- ◆ SKU1 support NFC function

Except Listings above, the others are the same as previous version.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely yours,



Contact Person: Won Chul Chang

Applicant: HMD Global Oy

E-Mail: won.chang@hmdglobal.com