

11 September 2018

Federal Communication Commission
Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

Certification and Engineering Bureau
Industry Canada
Spectrum Engineering Branch
3701 Carling Avenue, Building 94
Ottawa, Ontario K2H 8S2

PCII Request / Re-assessment

Multiview Media, FCC ID: <2AJW5MVMDISPLAY > granted on <16/08/2017>
and IC: <21979-MVMDISPLAY> granted on <18/06/2017>

TO WHOM IT MAY CONCERN

Pursuant to CFR § 2.1043 and RSP-100, <CONTINENTAL AUTOMOTIVE GMBH> hereby requests a Permissive Change Class II / Re-assessment.

Reason:

Improvements within the production process

Modifications:

Change on the PCB:

- Add 2 dampers
- Add additional resistors
- Add solder paste flow arrow (DCR)

Change of the production process:

- integration of Thermal paste station introduction in the assembly line

The following new exhibits will be uploaded:

- Change description document
- Schematics
- Component Layouts

Sincerely,

<SIGNATURE>

<NAME, TITLE> Dr. Marion Grüner (Homologation Manager)

<COMPANY NAME> CONTINENTAL AUTOMOTIVE GMBH

<ADDRESS> Heinrich-Hertz- Str. 45, 78052 Villingen- schwenningen, Germany

<PHONE NO.>+ 49 7721/ 67 2802