

Timco Engineering, Inc.
Product Certification
13146 NW 86th Drive Suite 400 Alachua,
FL 32615

Date: 20 December 2023

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: FCC ID:2AJYU-8XS0004

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

Per 2.933(b)


- 1.) The original identification is: FCC ID:2AJYU-8XS0003
- 2.) The original granted date is: 12/14/2023
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Label and Location Info

Sincerely,

Signatory



Name: yongsheng Li
Title: Deputy General Manager
SIMCom Wireless Solutions Limited
E-mail: yongsheng.li@simcom.com