## Rentokil Initial

Rentokil Initial 1927 plc Riverbank Meadows Business Park Camberley Surrey GU17 9AB T: +44 (0) 1276 607444

## **CLASS II PERMISSIVE CHANGE REQUEST**

7<sup>th</sup> June 2018

Element Materials Technology 100 Frobisher Business Park Leigh Sinton Road Malvern, Worcestershire WR14 1BX UK

RE:

Class II Permissive Change Request

FCC ID: 2AK3PGSD-500349

To Whom It May Concern:

Please be advised that pursuant to FCC Rule 47CFR 2.1043 the manufacturer requests that the above-referenced model be approved for class II permissive change.

The reason for the class II change is adding a new host Dual Autogate Connect (304854) to the Limited Module Approval covering the above LoRa module and reducing the power setting to 0x0C.

Thank you for your attention to this matter.

Yours faithfully

NPan

Rentokil Initial 1927 plc

Ning Pan