Rentokil Initial 1927 plc Request for Class II Permissive Change

FCC ID: 2AK3PGSD-500349

Date: 19th November 2018

TO: Federal Communication Commission

Please be notified that we, the undersigned, Rentokil Initial 1927 plc declare that the reasons for this Class II permissive change are as below:

The LoRa radio (RF part), module board, electrical circuit design, layout, components used and internal wiring are identical.

The internal antenna connected to the radio module, the host processor which controls the radio module are different.

The reason we are requesting a class II change is to add a new host to the approval as follows:

304838 = RADAR Single Connect 304840 = RADAR Dual Connect

Thank you. Sincerely.

Printed name: Adam O'Callaghan