



To whom it may concern:

The new Model: MX101 has following difference compared to certified Model: PX101C

Besides the exterior housing change for better look, added magnetometer (MAG3110) to determine door position.

10Pin and 4 pin FFC connector changed to robust FFC connector type.

All other parts, PCB traces and connectors are identical to the previous model.

Jon P. Torre

Director of Engineering