


45°

PCB-MP500
REV C

SEAL TEST
LATER
1.7hr T4 4/7/14
FAIL

30 31 32 33 34 35 36 37 38 39 40 41 42 43

7 8 9 10 11 12 13 14 15 16



3hr T4 4/7/14
FAIL

22µF100V-22
100V 22µF100

34 35 36 37 38 39 40 41 42

7 8 9 10 11 12 13

45°

1742M1670



