

Report No.: EED32P81818401 Page 48 of 68

9 PHOTOGRAPHS OF EUT Constructional Details



View of Product-1



View of Product-2





Report No.: EED32P81818401 Page 49 of 68



View of Product-3



View of Product-4













Report No.: EED32P81818401 Page 50 of 68



View of Product-5



View of Product-6





Page 51 of 68 Report No.: EED32P81818401



View of Product-7



View of Product-8(Ear L)













Report No.: EED32P81818401 Page 52 of 68



View of Product-9(Ear L)



View of Product-10(Ear L)













Report No.: EED32P81818401 Page 53 of 68



View of Product-11(Ear L)



View of Product-12(Ear L)














Report No.: EED32P81818401 Page 54 of 68



View of Product-13(Ear L)



View of Product-14(Ear L)














Report No.: EED32P81818401 Page 55 of 68



View of Product-15(Ear L)



View of Product-16(Ear R)













Report No.: EED32P81818401 Page 56 of 68



View of Product-17(Ear R)



View of Product-18(Ear R)













Report No.: EED32P81818401 Page 57 of 68



View of Product-19(Ear R)



View of Product-20(Ear R)













Report No.: EED32P81818401 Page 58 of 68



View of Product-21(Ear R)



View of Product-22(Ear R)













Report No.: EED32P81818401 Page 59 of 68



View of Product-23(Ear R)



View of Product-24






Report No.: EED32P81818401 Page 60 of 68



View of Product-25



View of Product-26









