

**CFR 47 FCC PART 15 SUBPART C**

**TEST REPORT**

*For*

**SmartSet Clock Radio**

**MODEL NUMBER: ER100301**

**Brand: EMERSON**

**REPORT NUMBER: E04A23070370F00304**

**ISSUE DATE: August 12, 2023**

*Prepared for*

**Emerson Radio Corp.**

**959 Route 46 East, Suite 210, 2nd Floor, Parsippany, NJ 07054, United States**

*Prepared by*

**Guangdong Global Testing Technology Co., Ltd.**

**Room 101-105, 203-210, Building 1, No.2, Keji 8 Road, Songshan Lake Park, Dongguan city, Guangdong, People's Republic of China, 523808**

**This report shall not be reproduced, except in full, without the written approval of  
Guangdong Global Testing Technology Co., Ltd.**

Revision History

<u>Rev.</u>	<u>Issue Date</u>	<u>Revisions</u>	<u>Revised By</u>
<u>V0</u>	<u>August 12, 2023</u>	<u>Initial Issue</u>	<u>Jok Yang</u>

## Appendix A PHOTOGRAPHS OF THE EUT

External-1



External-2



External-3



External-4



**External-5**



**External-6**



External-7




External-8




Internal-1




Internal-2



Internal-3



Internal-4






Internal-5



Internal-6




Internal-7



Internal-8




Internal-9



Internal-10

Antenna



RF IC

**--- END OF REPORT---**