## April. 24, 2017

Subject: Tuning and Adjustment of Signal booster, FCC ID 2ALGRPLX-GV70

There are no external tuning adjustments, The amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Fuynan Zhang

Fuyuan Zhang