


### Appendix C - BAND EDGES


Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:12:34

Band 2\_1.4 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:12:59

### Band 2\_1.4 MHz\_High\_QPSK




Date: 3.NOV.2022 18:15:10

### Band 2\_1.4 MHz\_High\_16QAM




Date: 3.NOV.2022 18:18:39

### Band 2\_3 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:21:20

### Band 2\_3 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:21:46

### Band 2\_3 MHz\_High\_QPSK




Date: 3.NOV.2022 18:22:51

### Band 2\_3 MHz\_High\_16QAM




Date: 3.NOV.2022 18:23:17

### Band 2\_5 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:24:37

### Band 2\_5 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:25:03

### Band 2\_5 MHz\_High\_QPSK




Date: 3.NOV.2022 18:26:01

### Band 2\_5 MHz\_High\_16QAM




Date: 3.NOV.2022 18:26:26

### Band 2\_10 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:27:39

### Band 2\_10 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:28:05

### Band 2\_10 MHz\_High\_QPSK



Date: 3.NOV.2022 18:29:07


### Band 2\_10 MHz\_High\_16QAM



Date: 3.NOV.2022 18:29:33




### Band 2\_15 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:30:36

### Band 2\_15 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:31:06

### Band 2\_15 MHz\_High\_QPSK




Date: 3.NOV.2022 18:32:16

### Band 2\_15 MHz\_High\_16QAM




Date: 3.NOV.2022 18:32:46

### Band 2\_20 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:33:37

### Band 2\_20 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:34:02

### Band 2\_20 MHz\_High\_QPSK




Date: 3.NOV.2022 18:35:04

### Band 2\_20 MHz\_High\_16QAM




Date: 3.NOV.2022 18:35:29

Band 4\_1.4 MHz\_Low\_QPSK




Date: 4.NOV.2022 08:01:42

Band 4\_1.4 MHz\_Low\_16QAM




Date: 4.NOV.2022 08:03:26

### Band 4\_1.4 MHz\_High\_QPSK




Date: 3.NOV.2022 18:38:51

### Band 4\_1.4 MHz\_High\_16QAM




Date: 3.NOV.2022 18:39:17

### Band 4\_3 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:42:01

### Band 4\_3 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:42:26

### Band 4\_3 MHz\_High\_QPSK



Date: 3.NOV.2022 18:43:38


### Band 4\_3 MHz\_High\_16QAM



Date: 3.NOV.2022 18:44:03




### Band 4\_5 MHz\_Low\_QPSK




Date: 3.NOV.2022 18:52:13

### Band 4\_5 MHz\_Low\_16QAM




Date: 3.NOV.2022 18:52:39

### Band 4\_5 MHz\_High\_QPSK




Date: 3.NOV.2022 18:53:56

### Band 4\_5 MHz\_High\_16QAM




Date: 3.NOV.2022 18:54:21

### Band 4\_10 MHz\_Low\_QPSK




Date: 3.NOV.2022 19:02:13

### Band 4\_10 MHz\_Low\_16QAM




Date: 3.NOV.2022 19:02:39

### Band 4\_10 MHz\_High\_QPSK




Date: 4.NOV.2022 08:06:27

### Band 4\_10 MHz\_High\_16QAM




Date: 4.NOV.2022 08:06:52

### Band 4\_15 MHz\_Low\_QPSK




Date: 4.NOV.2022 08:08:07

### Band 4\_15 MHz\_Low\_16QAM




Date: 4.NOV.2022 08:08:32

### Band 4\_15 MHz\_High\_QPSK




Date: 4.NOV.2022 08:09:48

### Band 4\_15 MHz\_High\_16QAM




Date: 4.NOV.2022 08:10:13

### Band 4\_20 MHz\_Low\_QPSK



Date: 4.NOV.2022 08:25:41

### Band 4\_20 MHz\_Low\_16QAM



Date: 4.NOV.2022 08:18:13