



### Band 25\_3 MHz\_Low\_QPSK




Date: 4.NOV.2022 09:53:06

### Band 25\_3 MHz\_Low\_16QAM




Date: 4.NOV.2022 09:53:30

### Band 25\_3 MHz\_High\_QPSK




Date: 4.NOV.2022 09:54:18

### Band 25\_3 MHz\_High\_16QAM




Date: 4.NOV.2022 09:54:42

### Band 25\_5 MHz\_Low\_QPSK




Date: 4.NOV.2022 09:56:54

### Band 25\_5 MHz\_Low\_16QAM




Date: 4.NOV.2022 09:57:19

### Band 25\_5 MHz\_High\_QPSK




Date: 4.NOV.2022 09:58:45

### Band 25\_5 MHz\_High\_16QAM




Date: 4.NOV.2022 09:59:10

### Band 25\_10 MHz\_Low\_QPSK




Date: 4.NOV.2022 10:01:19

### Band 25\_10 MHz\_Low\_16QAM




Date: 4.NOV.2022 10:01:43

### Band 25\_10 MHz\_High\_QPSK




Date: 4.NOV.2022 13:05:46

### Band 25\_10 MHz\_High\_16QAM




Date: 4.NOV.2022 13:07:30

### Band 25\_15 MHz\_Low\_QPSK




Date: 4.NOV.2022 10:10:07

### Band 25\_15 MHz\_Low\_16QAM




Date: 4.NOV.2022 10:10:31

### Band 25\_15 MHz\_High\_QPSK



Date: 4.NOV.2022 10:11:12


### Band 25\_15 MHz\_High\_16QAM



Date: 4.NOV.2022 10:11:37




### Band 25\_20 MHz\_Low\_QPSK




Date: 4.NOV.2022 10:13:39

### Band 25\_20 MHz\_Low\_16QAM




Date: 4.NOV.2022 10:14:04

### Band 25\_20 MHz\_High\_QPSK




Date: 4.NOV.2022 10:14:52

### Band 25\_20 MHz\_High\_16QAM




Date: 4.NOV.2022 10:17:42

Part 22H\_Band 26\_1.4 MHz\_Low\_QPSK




Date: 4.NOV.2022 14:27:06

Part 22H\_Band 26\_1.4 MHz\_Low\_16QAM




Date: 4.NOV.2022 14:27:31

Part 22H\_Band 26\_1.4 MHz\_High\_QPSK




Date: 4.NOV.2022 14:30:00

Part 22H\_Band 26\_1.4 MHz\_High\_16QAM




Date: 4.NOV.2022 14:30:24

Part 22H\_Band 26\_3 MHz\_Low\_QPSK




Date: 4.NOV.2022 14:34:16

Part 22H\_Band 26\_3 MHz\_Low\_16QAM




Date: 4.NOV.2022 14:34:41

Part 22H\_Band 26\_3 MHz\_High\_QPSK




Date: 4.NOV.2022 14:35:29

Part 22H\_Band 26\_3 MHz\_High\_16QAM




Date: 4.NOV.2022 14:35:53

Part 22H\_Band 26\_5 MHz\_Low\_QPSK




Date: 4.NOV.2022 14:36:43

Part 22H\_Band 26\_5 MHz\_Low\_16QAM




Date: 4.NOV.2022 14:37:08

Part 22H\_Band 26\_5 MHz\_High\_QPSK



Date: 4.NOV.2022 14:37:56


Part 22H\_Band 26\_5 MHz\_High\_16QAM



Date: 4.NOV.2022 14:38:20




Part 22H\_Band 26\_10 MHz\_Low\_QPSK




Date: 4.NOV.2022 14:40:42

Part 22H\_Band 26\_10 MHz\_Low\_16QAM




Date: 4.NOV.2022 14:41:07

Part 22H\_Band 26\_10 MHz\_High\_QPSK




Date: 4.NOV.2022 14:55:29

Part 22H\_Band 26\_10 MHz\_High\_16QAM




Date: 4.NOV.2022 14:43:38

Part 22H\_Band 26\_15 MHz\_Low\_QPSK




Date: 4.NOV.2022 14:47:21

Part 22H\_Band 26\_15 MHz\_Low\_16QAM




Date: 4.NOV.2022 14:49:37

Part 22H\_Band 26\_15 MHz\_High\_QPSK




Date: 4.NOV.2022 14:50:50

Part 22H\_Band 26\_15 MHz\_High\_16QAM




Date: 4.NOV.2022 14:51:15

Part 90\_Band 26\_1.4 MHz\_Low\_QPSK




Date: 4.NOV.2022 16:40:09

Part 90\_Band 26\_1.4 MHz\_Low\_16QAM




Date: 4.NOV.2022 16:39:32

Part 90\_Band 26\_1.4 MHz\_High\_QPSK




Date: 4.NOV.2022 16:37:07

Part 90\_Band 26\_1.4 MHz\_High\_16QAM




Date: 4.NOV.2022 16:37:57

Part 90\_Band 26\_3 MHz\_Low\_QPSK



Date: 4.NOV.2022 16:32:29

Part 90\_Band 26\_3 MHz\_Low\_16QAM



Date: 4.NOV.2022 16:33:05