



Part 90_Band 26_3 MHz_High_QPSK




Date: 4.NOV.2022 16:34:54

Part 90_Band 26_3 MHz_High_16QAM




Date: 4.NOV.2022 16:35:44

Part 90_Band 26_5 MHz_Low_QPSK




Date: 4.NOV.2022 16:28:47

Part 90_Band 26_5 MHz_Low_16QAM




Date: 4.NOV.2022 16:29:49

Part 90_Band 26_5 MHz_High_QPSK




Date: 4.NOV.2022 16:27:07

Part 90_Band 26_5 MHz_High_16QAM




Date: 4.NOV.2022 16:25:59

Part 90_Band 26_10 MHz_Middle_QPSK



Date: 4.NOV.2022 16:42:47

Part 90_Band 26_10 MHz_Middle_16QAM




Date: 4.NOV.2022 16:43:30

Band 66_1.4 MHz_Low_QPSK




Date: 4.NOV.2022 10:20:04

Band 66_1.4 MHz_Low_16QAM




Date: 4.NOV.2022 10:22:13

Band 66_1.4 MHz_High_QPSK




Date: 4.NOV.2022 10:23:45

Band 66_1.4 MHz_High_16QAM




Date: 4.NOV.2022 10:24:10

Band 66_3 MHz_Low_QPSK




Date: 4.NOV.2022 10:26:07

Band 66_3 MHz_Low_16QAM




Date: 4.NOV.2022 10:26:31

Band 66_3 MHz_High_QPSK




Date: 4.NOV.2022 13:11:52

Band 66_3 MHz_High_16QAM




Date: 4.NOV.2022 10:29:00

Band 66_5 MHz_Low_QPSK




Date: 4.NOV.2022 10:30:58

Band 66_5 MHz_Low_16QAM




Date: 4.NOV.2022 10:31:22

Band 66_5 MHz_High_QPSK




Date: 4.NOV.2022 13:19:31

Band 66_5 MHz_High_16QAM




Date: 4.NOV.2022 10:42:47

Band 66_10 MHz_Low_QPSK




Date: 4.NOV.2022 10:48:10

Band 66_10 MHz_Low_16QAM




Date: 4.NOV.2022 10:48:35

Band 66_10 MHz_High_QPSK




Date: 4.NOV.2022 10:50:02

Band 66_10 MHz_High_16QAM




Date: 4.NOV.2022 10:50:26

Band 66_15 MHz_Low_QPSK




Date: 4.NOV.2022 10:52:57

Band 66_15 MHz_Low_16QAM




Date: 4.NOV.2022 10:53:22

Band 66_15 MHz_High_QPSK




Date: 4.NOV.2022 10:54:10

Band 66_15 MHz_High_16QAM




Date: 4.NOV.2022 10:54:35

Band 66_20 MHz_Low_QPSK




Date: 4.NOV.2022 13:24:40

Band 66_20 MHz_Low_16QAM




Date: 4.NOV.2022 13:26:39

Band 66_20 MHz_High_QPSK




Date: 4.NOV.2022 10:57:27

Band 66_20 MHz_High_16QAM




Date: 4.NOV.2022 10:57:52

Band 85_5 MHz_Low_QPSK




Date: 4.NOV.2022 12:14:34

Band 85_5 MHz_Low_16QAM




Date: 4.NOV.2022 12:14:58

Band 85_5 MHz_High_QPSK




Date: 4.NOV.2022 12:17:44

Band 85_5 MHz_High_16QAM




Date: 4.NOV.2022 12:18:09

Band 85_10 MHz_Low_QPSK




Date: 4.NOV.2022 12:22:14

Band 85_10 MHz_Low_16QAM




Date: 4.NOV.2022 12:22:39

Band 85_10 MHz_High_QPSK



Date: 4.NOV.2022 12:24:03

Band 85_10 MHz_High_16QAM



Date: 4.NOV.2022 12:24:27