



## Appendix B: Conducted Spurious Emissions

### 101 Band 2\_1.4 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:37:41

### 102 Band 2\_1.4 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:46:20

### 201 Band 2\_1.4 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:38:21

### 202 Band 2\_1.4 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:45:59

### 301 Band 2\_1.4 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:42:24

### 302 Band 2\_1.4 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:48:41

### 401 Band 2\_3 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:42:47

### 402 Band 2\_3 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:41:02

### 501 Band 2\_3 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:43:04

### 502 Band 2\_3 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:46:40

### 601 Band 2\_3 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:43:21

### 602 Band 2\_3 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:49:05

### 701 Band 2\_5 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:43:37

### 702 Band 2\_5 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:42:31

### 801 Band 2\_5 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:44:01

### 802 Band 2\_5 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:47:03

### 901 Band 2\_5 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:44:17

### 902 Band 2\_5 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:49:30

### 1001 Band 2\_10 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:45:04

### 1002 Band 2\_10 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:43:09

### 1101 Band 2\_10 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:45:21

### 1102 Band 2\_10 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:47:24

### 1201 Band 2\_10 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:45:37

### 1202 Band 2\_10 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:49:56

### 1301 Band 2\_15 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:46:21

### 1302 Band 2\_15 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:43:51

### 1401 Band 2\_15 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:46:49

### 1402 Band 2\_15 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:47:49

### 1501 Band 2\_15 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:48:11

### 1502 Band 2\_15 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:50:27

1601 Band 2\_20 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:49:18

1602 Band 2\_20 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:44:51

### 1701 Band 2\_20 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:51:37

### 1702 Band 2\_20 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:48:16

### 1801 Band 2\_20 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:52:13

### 1802 Band 2\_20 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:50:58

### 1901 Band 5\_1.4 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:53:51

### 1902 Band 5\_1.4 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:33:19

### 2001 Band 5\_1.4 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:03:48

### 2002 Band 5\_1.4 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:33:39

### 2101 Band 5\_1.4 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:03:08

### 2102 Band 5\_1.4 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:34:04

### 2201 Band 5\_3 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:54:58

### 2202 Band 5\_3 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:34:34

### 2301 Band 5\_3 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:00:06

### 2302 Band 5\_3 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:35:26

### 2401 Band 5\_3 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:27:44

### 2402 Band 5\_3 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:35:51

### 2501 Band 5\_5 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:55:51

### 2502 Band 5\_5 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:36:12

### 2601 Band 5\_5 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:00:41

### 2602 Band 5\_5 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:36:40

### 2701 Band 5\_5 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:28:39

### 2702 Band 5\_5 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:37:09

### 2801 Band 5\_10 MHz\_Low\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 15:58:26

### 2802 Band 5\_10 MHz\_Low\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:37:38

### 2901 Band 5\_10 MHz\_Middle\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:01:37

### 2902 Band 5\_10 MHz\_Middle\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:38:09

### 3001 Band 5\_10 MHz\_High\_QPSK(30MHz-1GHz)




Date: 8.JUN.2024 16:29:16

### 3002 Band 5\_10 MHz\_High\_QPSK(1GHz-20GHz)




Date: 8.JUN.2024 16:38:44

101 Band 4\_1.4 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:22:22

102 Band 4\_1.4 MHz\_Low\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:22:32

### 201 Band 4\_1.4 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:22:47

### 202 Band 4\_1.4 MHz\_Middle\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:22:57

301 Band 4\_1.4 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:23:10

302 Band 4\_1.4 MHz\_High\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:23:52

### 401 Band 4\_3 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:36:36

### 402 Band 4\_3 MHz\_Low\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:36:46

501 Band 4\_3 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:36:59

502 Band 4\_3 MHz\_Middle\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:37:09

601 Band 4\_3 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:37:24

602 Band 4\_3 MHz\_High\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:37:34

### 701 Band 4\_5 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:56:41

### 702 Band 4\_5 MHz\_Low\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:56:51

### 801 Band 4\_5 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:57:09

### 802 Band 4\_5 MHz\_Middle\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:57:19

### 901 Band 4\_5 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:57:33

### 902 Band 4\_5 MHz\_High\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 14:57:44

### 1001 Band 4\_10 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 14:59:53

### 1002 Band 4\_10 MHz\_Low\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:00:03

### 1101 Band 4\_10 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:00:18

### 1102 Band 4\_10 MHz\_Middle\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:00:28

### 1201 Band 4\_10 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:00:43

### 1202 Band 4\_10 MHz\_High\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:00:53

1301 Band 4\_15 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:02:12

1302 Band 4\_15 MHz\_Low\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:02:22

### 1401 Band 4\_15 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:02:45

### 1402 Band 4\_15 MHz\_Middle\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:02:55

### 1501 Band 4\_15 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:03:15

### 1502 Band 4\_15 MHz\_High\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:03:25

1601 Band 4\_20 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:04:41

1602 Band 4\_20 MHz\_Low\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:04:51

1701 Band 4\_20 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:05:14

1702 Band 4\_20 MHz\_Middle\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:05:24

### 1801 Band 4\_20 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:05:44

### 1802 Band 4\_20 MHz\_High\_QPSK\_2(1GHz-20GHz)




Date: 8.JUN.2024 15:05:54

1901 Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:08:02

1902 Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:08:12

## 2001 Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:08:26

## 2002 Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:08:36

2101 Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:08:52

2102 Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:09:02

2201 Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:10:20

2202 Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:10:30

2301 Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:10:46

2302 Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:10:57

### 2401 Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:11:10

### 2402 Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:11:20

2501 Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:12:28

2502 Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:12:39

2601 Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:12:53

2602 Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:13:03

2701 Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:13:17

2702 Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:13:28

### 2801 Band 12\_10 MHz\_Low\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:14:47

### 2802 Band 12\_10 MHz\_Low\_QPSK\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:14:57

### 2901 Band 12\_10 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:15:12

### 2902 Band 12\_10 MHz\_Middle\_QPSK\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:15:22

### 3001 Band 12\_10 MHz\_High\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:15:40

### 3002 Band 12\_10 MHz\_High\_QPSK\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:15:50

3101 Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:16:57

3102 Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:17:07

3103 Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 28.JUN.2024 09:47:44

3104 Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_4(793MHz-806MHz)




Date: 8.JUN.2024 15:17:33

### 3105 Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_5(1.5590GHz-1.61GHz)




Date: 8.JUN.2024 15:17:43

### 3201 Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:17:57

3202 Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:18:07

3203 Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 8.JUN.2024 15:18:20

3204 Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_4(793MHz-806MHz)




Date: 8.JUN.2024 15:18:33

3205 Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_5(1.559GHz-1.61GHz)




Date: 8.JUN.2024 15:18:47

### 3301 Band 13\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:19:04

### 3302 Band 13\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:19:14

3303 Band 13\_5 MHz\_High\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 8.JUN.2024 15:19:27

3304 Band 13\_5 MHz\_High\_QPSK\_RB25#0\_4(793MHz-806MHz)




Date: 8.JUN.2024 15:19:40

3305 Band 13\_5 MHz\_High\_QPSK\_RB25#0\_5(1.5590GHz-1.61GHz)




Date: 8.JUN.2024 15:19:53

3401 Band 13\_10 MHz\_Middle\_QPSK\_1(30MHz-1GHz)




Date: 8.JUN.2024 15:21:23

### 3402 Band 13\_10 MHz\_Middle\_QPSK\_2(1GHz-10GHz)




Date: 8.JUN.2024 15:21:33

### 3403 Band 13\_10 MHz\_Middle\_QPSK\_3(763MHz-775MHz)




Date: 28.JUN.2024 09:54:17

3404 Band 13\_10 MHz\_Middle\_QPSK\_4(793MHz-806MHz)




Date: 8.JUN.2024 15:21:56

3405 Band 13\_10 MHz\_Middle\_QPSK\_5(1.5590GHz-1.61GHz)




Date: 8.JUN.2024 15:22:06

### 1 Band 25\_1.4 MHz\_Low\_QPSK\_1@0




Date: 28.JUN.2024 10:02:25

### 2 Band 25\_1.4 MHz\_Mid\_QPSK\_1@0




Date: 24.JUN.2024 11:55:19

### 3 Band 25\_1.4 MHz\_High\_QPSK\_1@0




Date: 24.JUN.2024 11:55:39

### 4 Band 25\_3 MHz\_Low\_QPSK\_1@0




Date: 24.JUN.2024 11:57:31

### 5 Band 25\_3 MHz\_Mid\_QPSK\_1@0




Date: 24.JUN.2024 11:57:53

### 6 Band 25\_3 MHz\_High\_QPSK\_1@0




Date: 24.JUN.2024 11:58:14

### 7 Band 25\_5 MHz\_Low\_QPSK\_1@0




Date: 24.JUN.2024 12:00:04

### 8 Band 25\_5 MHz\_Mid\_QPSK\_1@0




Date: 24.JUN.2024 12:00:26

### 9 Band 25\_5 MHz\_High\_QPSK\_1@0




Date: 24.JUN.2024 12:00:47

### 10 Band 25\_10 MHz\_Low\_QPSK\_1@0




Date: 24.JUN.2024 12:03:14

### 11 Band 25\_10 MHz\_Mid\_QPSK\_1@0




Date: 24.JUN.2024 12:03:35

### 12 Band 25\_10 MHz\_High\_QPSK\_1@0




Date: 24.JUN.2024 12:03:56

### 13 Band 25\_15 MHz\_Low\_QPSK\_1@0




Date: 24.JUN.2024 12:11:20

### 14 Band 25\_15 MHz\_Mid\_QPSK\_1@0




Date: 24.JUN.2024 12:11:42

### 15 Band 25\_15 MHz\_High\_QPSK\_1@0




Date: 24.JUN.2024 12:12:03

### 16 Band 25\_20 MHz\_Low\_QPSK\_1@0




Date: 24.JUN.2024 12:13:39

### 17 Band 25\_20 MHz\_Mid\_QPSK\_1@0



Date: 24.JUN.2024 12:14:01


### 18 Band 25\_20 MHz\_High\_QPSK\_1@0



Date: 24.JUN.2024 12:14:23


Band 26(Part 90S):

Band 26\_1.4 MHz\_High\_QPSK




Date: 24.JUN.2024 13:06:06

Band 26\_1.4 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:05:24

### Band 26\_1.4 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:05:45

### Band 26\_3 MHz\_High\_QPSK




Date: 24.JUN.2024 13:07:11

### Band 26\_3 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:06:29

### Band 26\_3 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:06:50

### Band 26\_5 MHz\_High\_QPSK




Date: 24.JUN.2024 13:08:15

### Band 26\_5 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:07:34

### Band 26\_5 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:07:55

### Band 26\_10 MHz\_High\_QPSK




Date: 24.JUN.2024 13:09:21

### Band 26\_10 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:08:40

### Band 26\_10 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:09:00

### Band 26\_15 MHz\_Low\_QPSK



Date: 24.JUN.2024 13:13:53


### Band 26\_15 MHz\_Mid\_QPSK



Date: 14.JUN.2024 19:51:27


Band 26(Part 22H):

Band 26\_1.4 MHz\_High\_QPSK




Date: 24.JUN.2024 13:41:51

Band 26\_1.4 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:41:08

### Band 26\_1.4 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:41:30

### Band 26\_3 MHz\_High\_QPSK




Date: 24.JUN.2024 13:44:32

### Band 26\_3 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:43:47

### Band 26\_3 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:44:10

### Band 26\_5 MHz\_High\_QPSK




Date: 24.JUN.2024 13:47:33

### Band 26\_5 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:46:51

### Band 26\_5 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:47:12

### Band 26\_10 MHz\_High\_QPSK




Date: 24.JUN.2024 13:58:45

### Band 26\_10 MHz\_Low\_QPSK




Date: 24.JUN.2024 13:57:59

### Band 26\_10 MHz\_Mid\_QPSK




Date: 24.JUN.2024 13:58:23

### Band 26\_15 MHz\_High\_QPSK




Date: 24.JUN.2024 14:01:13

### Band 26\_15 MHz\_Low\_QPSK



Date: 24.JUN.2024 14:00:29

Band 26\_15 MHz\_Mid\_QPSK



Date: 24.JUN.2024 14:00:51