Report No.: 17010363JNA-003


FCC ID :2ALNEGTDMBN ISED CN and UPN :4361A-GTDMBN

# <u>APPENDIX</u>

# Photographs

#### FCC ID :2ALNEGTDMBN ISED CN and UPN :4361A-GTDMBN PHOTOGRAPHS OF MAXIMUM EMISSION SET-UP

# 1. Conducted disturbance at mains terminals






Original: June 5, 2017 Revised: June 14, 2017

FCC ID :2ALNEGTDMBN ISED CN and UPN :4361A-GTDMBN


2. Radiated disturbance (X axis)





# Radiated disturbance (Y axis)






Radiated disturbance (Z axis)





### 3. Above 1 GHz



Note : Maintaining 10cm spacing between all the equipment cabinets.

Report No.: 17010363JNA-003

FCC ID :2ALNEGTDMBN ISED CN and UPN :4361A-GTDMBN

# 3.1 Measurement Set-up (Above 1 GHz)



## 4. Frequency Tolerance

