




Top




L2\_GND







# L4\_SIG2/GND




L5\_PWR/GND



Bottom




# Assembly Top




U5


# Assembly Value




# Solder Mask Top




# Paste Mask Top



# Solder Mask Bottom



# Paste Mask Bottom



# Drill Draw

