

Shen Zhen ANNTLENT Communication Technology co., Ltd.

Feb. 10, 2023

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2ALZECL70VA-01

There are no external tuning adjustments, The amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Sam Sun

Sam Sun