

**Shen Zhen ANNTLENT Communication Technology co., Ltd.**

Aug 31, 2020

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2ALZECPL70A

There are no external tuning adjustments, The amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Sam Sun

*Sam Sun*