

SETUP PHOTOS

Report Number.: 13757234-EP1V1

Applicant: Magic Leap Inc.

7500 West Sunrise Blvd Plantation, FL, 33322, US

Model : M2003000, M2004000, M2005000, M2103000,

M2104000, M2105000

Brand: Magic Leap Inc.

FCC ID : 2AM5N-ML2M2

IC: 23045-ML2M2

EUT Description: Magic Leap 2 Controller with BLE transceiver

Test Standard(s): FCC 47 CFR PART 15 SUBPART C

ISED RSS-247 ISSUE 2

ISED RSS-GEN ISSUE 5 + A1 + A2

Date of Issue:

May 05, 2022

Prepared by:

UL VERIFICATION SERVICES 47173 Benicia Street Fremont, CA 94538 U.S.A.

TEL: (510) 319-4000 FAX: (510) 661-0888





REPORT NO: 13757234-EP1V1 DATE: 5/5/2022 FCC ID: 2AM5N-ML2M2 IC: 23045-ML2M2

REVISION HISTORY

Rev.	Issue Date	Revisions	Revised By
V1	5/5/2022	Initial Issue	

TABLE OF CONTENTS


RE	VISION HISTORY	. 2
TAE	BLE OF CONTENTS	.3
1.	SETUP PHOTOS	.4

DATE: 5/5/2022

IC: 23045-ML2M2

1. SETUP PHOTOS

ANTENNA PORT AND AC LINE CONDUCTED SETUP






AC LINE CONDUCTED (FRONT)



AC LINE CONDUCTED (BACK)

RADIATED RF MEASUREMENT SETUP




Page 5 of 6


DATE: 5/5/2022

IC: 23045-ML2M2

ORIENTATIONS







END OF TEST REPORT