


MPOW TECHNOLOGY CO., LIMITED  
 ADD: FLAT/RM 605 6/F FA YUEN COMMERCIAL BUILDING 75-77 FA YUEN STREET MONGKOK KL HONG KONG  
 TEL: 18566621145  
 FAX: +86-755-26008484  
 Mail: Derric\_bai@patazon.net

**To**  
**FEDERAL COMMUNICATIONS COMMISSION**  
 Authorization and Evaluation Division  
 7435 Oakland Mills Road  
 Columbia,MD 21046

Dear Sir/Madam,

We, MPOW TECHNOLOGY CO., LIMITED, FCC ID: 2AMH2-BH413A, hereby submits justification for placing the FCC ID label to the charging box. According to the FCC Regulation and Guidance (KDB Publication 784748 D01 v09R01) allows for the FCC to be removed to charging box if the device is unquestionably too small for the FCC ID label to be printed.

The measurement of headset: Length (42.6mm)\*Width (22.8mm)\*High (23mm), label: Length45(mm)\*Width23(mm), charging box:81.46(mm)\*38 (mm)\*28.2(mm).Refer to the above quote, as the headset are too small for the FCC ID label to be printed, so the FCC ID label will be moved to the charging box. For details, please see below photos:



Sincerely,

*Derric Bai*

Derric Bai  
 Compliance Manager  
 Date: 2019-11-12  
 QA-FR-169-B