

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR

INTERNAL PHOTOGRAPHS



Figure 1. EUT Open

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR



Figure 2. PCB View

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR



Figure 3. 2.4 GHz ISM Radio Module

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR




Figure 4. PCB Component View

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR




Figure 5. PCB Rear View

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR



Figure 6. UWB Radio Module

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR




Figure 7. UWB Radio Module with Shield Removed

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR




Figure 8. Back of UWB Radio Module

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15 Certification
2AMOW-AR002HLR
17-0277
October 2, 2017
Sanitag Technologies Corp
AR-002-HLR




Figure 9. 2.4 GHz Radio Antenna