



Please refer to following plots:




Date: 26.OCT.2022 17:49:06




Date: 26.OCT.2022 17:49:12

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 26.OCT.2022 17:49:19

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 26.OCT.2022 17:49:26

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 26.OCT.2022 17:49:36

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 26.OCT.2022 17:49:42

Band 2_3 MHz_High_QPSK_RB15#0




Date: 26.OCT.2022 17:49:50

Band 2_3 MHz_High_16QAM_RB15#0




Date: 26.OCT.2022 17:49:57

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 26.OCT.2022 17:50:07

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 26.OCT.2022 17:50:13

Band 2_5 MHz_High_QPSK_RB25#0




Date: 26.OCT.2022 17:50:21

Band 2_5 MHz_High_16QAM_RB25#0




Date: 26.OCT.2022 17:50:29

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 26.OCT.2022 17:50:40

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 26.OCT.2022 17:50:47

Band 2_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:50:56

Band 2_10 MHz_High_16QAM_RB50#0




Date: 26.OCT.2022 17:51:04

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 26.OCT.2022 17:51:14

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 26.OCT.2022 17:51:21

Band 2_15 MHz_High_QPSK_RB75#0




Date: 26.OCT.2022 17:51:29

Band 2_15 MHz_High_16QAM_RB75#0




Date: 26.OCT.2022 17:51:36

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:51:47

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:51:54

Band 2_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:52:02

Band 2_20 MHz_High_16QAM_RB100#0




Date: 26.OCT.2022 17:52:09

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 26.OCT.2022 17:52:21

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 26.OCT.2022 17:52:28

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 26.OCT.2022 17:52:39

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 26.OCT.2022 17:52:45

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 26.OCT.2022 17:52:55

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 26.OCT.2022 17:53:02

Band 4_3 MHz_High_QPSK_RB15#0




Date: 26.OCT.2022 17:53:09

Band 4_3 MHz_High_16QAM_RB15#0




Date: 26.OCT.2022 17:53:15

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 26.OCT.2022 17:53:25

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 26.OCT.2022 17:53:32

Band 4_5 MHz_High_QPSK_RB25#0




Date: 26.OCT.2022 17:53:40

Band 4_5 MHz_High_16QAM_RB25#0




Date: 26.OCT.2022 17:53:47

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 26.OCT.2022 17:53:58

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 26.OCT.2022 17:54:06

Band 4_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:54:15

Band 4_10 MHz_High_16QAM_RB50#0




Date: 26.OCT.2022 17:54:22

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 26.OCT.2022 17:54:33

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 26.OCT.2022 17:54:40

Band 4_15 MHz_High_QPSK_RB75#0




Date: 26.OCT.2022 17:54:47

Band 4_15 MHz_High_16QAM_RB75#0




Date: 26.OCT.2022 17:54:54

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:55:05

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:55:12

Band 4_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:55:20

Band 4_20 MHz_High_16QAM_RB100#0




Date: 26.OCT.2022 17:55:27

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 27.OCT.2022 19:38:14

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 27.OCT.2022 19:38:38

Band 7_5 MHz_High_QPSK_RB25#0




Date: 27.OCT.2022 19:39:12

Band 7_5 MHz_High_16QAM_RB25#0




Date: 27.OCT.2022 19:39:38

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 27.OCT.2022 19:40:20

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 27.OCT.2022 19:40:41

Band 7_10 MHz_High_QPSK_RB50#0




Date: 27.OCT.2022 19:41:15

Band 7_10 MHz_High_16QAM_RB50#0




Date: 27.OCT.2022 19:41:40

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 27.OCT.2022 19:42:22

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 27.OCT.2022 19:42:40

Band 7_15 MHz_High_QPSK_RB75#0




Date: 27.OCT.2022 19:43:11

Band 7_15 MHz_High_16QAM_RB75#0




Date: 27.OCT.2022 19:43:43

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 27.OCT.2022 19:46:45

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 27.OCT.2022 19:47:08

Band 7_20 MHz_High_QPSK_RB100#0




Date: 27.OCT.2022 19:45:50


Band 7_20 MHz_High_16QAM_RB100#0



Date: 27.OCT.2022 19:46:16




Date: 27.OCT.2022 13:26:35




Date: 27.OCT.2022 13:26:41

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 27.OCT.2022 13:26:51

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 27.OCT.2022 13:26:57

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 27.OCT.2022 13:27:08

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 27.OCT.2022 13:27:15

Band 5_3 MHz_High_QPSK_RB15#0




Date: 27.OCT.2022 13:27:22

Band 5_3 MHz_High_16QAM_RB15#0




Date: 27.OCT.2022 13:27:28

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 27.OCT.2022 13:27:39

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 27.OCT.2022 13:27:45

Band 5_5 MHz_High_QPSK_RB25#0




Date: 27.OCT.2022 13:27:53

Band 5_5 MHz_High_16QAM_RB25#0




Date: 27.OCT.2022 13:27:59

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 27.OCT.2022 13:29:05

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 27.OCT.2022 13:29:12

Band 5_10 MHz_High_QPSK_RB50#0




Date: 27.OCT.2022 13:29:21

Band 5_10 MHz_High_16QAM_RB50#0




Date: 27.OCT.2022 13:29:29

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 27.OCT.2022 19:25:55

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 27.OCT.2022 19:26:20

Band 38_5 MHz_High_QPSK_RB25#0




Date: 27.OCT.2022 19:27:02

Band 38_5 MHz_High_16QAM_RB25#0




Date: 27.OCT.2022 19:27:48

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 27.OCT.2022 19:28:34

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 27.OCT.2022 19:29:03

Band 38_10 MHz_High_QPSK_RB50#0




Date: 27.OCT.2022 19:29:49

Band 38_10 MHz_High_16QAM_RB50#0




Date: 27.OCT.2022 19:30:26

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 27.OCT.2022 19:31:05

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 27.OCT.2022 19:31:32

Band 38_15 MHz_High_QPSK_RB75#0




Date: 27.OCT.2022 19:32:06

Band 38_15 MHz_High_16QAM_RB75#0




Date: 27.OCT.2022 19:32:27

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 27.OCT.2022 19:33:06

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 27.OCT.2022 19:33:22

Band 38_20 MHz_High_QPSK_RB100#0




Date: 27.OCT.2022 19:33:52

Band 38_20 MHz_High_16QAM_RB100#0




Date: 27.OCT.2022 19:34:09

Band 26_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2022 19:17:29

Band 26_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2022 19:17:59

Band 26_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2022 19:18:45

Band 26_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2022 19:19:06

Band 26_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2022 19:19:38

Band 26_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2022 19:20:08

Band 26_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2022 19:20:45

Band 26_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2022 19:21:12

Band 26_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2022 19:12:09

Band 26_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2022 19:13:50

Band 26_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2022 19:14:56

Band 26_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2022 19:15:17

Band 26_10 MHz_QPSK_RB50#0




Date: 4.NOV.2022 19:16:05

Band 26_10 MHz_16QAM_RB50#0




Date: 4.NOV.2022 19:16:30

Band 26_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2022 17:06:23

Band 26_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2022 17:06:30

Band 26_15 MHz_High_QPSK_RB75#0



Date: 4.NOV.2022 17:06:39

Band 26_15 MHz_High_16QAM_RB75#0



Date: 4.NOV.2022 17:06:46