

Thundercomm Technology Co., Ltd

Address: No. 107, Middle Datagu Road, Xiantao Street, Yubei District, Chongqing,
China, 401122

Tel: +86 010-82036511

Email: qiyong.zhou@thundercomm.com

Date: 2023-03-27

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division


7435 Oakland Mills Road

Columbia, MD 21046

Dear Sir/Madam,

The RF chip, model: WCN6856 installed in our product C6490, model: C6490-U4A, FCC ID: 2AOHHTURBOX-C6490, supports 2.4G Wi-Fi function, Used in the United States, this chip only supports 2.4G Wi-Fi (2412-2462MHz/2422-2452MHz). The other 2.4G Wi-Fi bands was disabled to use by manufacture in the software, the end user has no capability to activate it.

Sincerely Yours,

Signature: 

Contact person: Qiyong Zhou

Title: Manager