

Test Setup Photographs for the MARK 2 MR

1. Radiated Emissions

1.1. Configuration 1: Setup for masurement from 30 MHz to 1 GHz

Photo 1: MARK 2 MR + Glove (Long Life)





Photo 2: MARK 2 MR + Glove (Long Life)




Radiated Emissions (continued)

1.2. Configuration 1: Setup for masurement from 1 GHz to 18 GHz

Photo 3: MARK 2 MR + Glove (Long Life)



Photo 4: MARK 2 MR + Glove (Long Life)



2. Conducted Measurement

Photo 5: MARK 2 MR + Glove (Long Life)

