

TZUMI Electronics,LLC  
16 EAST 34TH STREET 16TH FLOOR NEW YORK, NY 10016 United States

---

**Date:** April 29, 2022

To:  
Federal Communication Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046


To Whom It May Concern,

Original **FCC ID:** [2ATOY-RT60](#); Model Number: RT60, 8702, 8701, 8700, 8702ST, 8701ST, 8700ST, 7554CT, 8159CT, 6759-2, 6759HD-2, 7693HD, 7697HD, 7776HD, 7697HDC, 7752PS, 7697PS, 8149PS, 7776, 7777, 7778, 7779, 7776NR, 7777NR, 6759TJX, 7776TJX, 7778TJX, 7779TJX, 7992TJX, 8434TJX, 8016WM, 8017WM, 8062JCP, 8048JCP, 8047JCP, 8046JCP, 8045JCP, 8044JCP, 7776JCP, 7777JCP, 7778JCP, 7779JCP, 7992JCP, 8352JCP, 8353JCP, 8223JCP, 8062JCE, 8048JCE, 8047JCE, 8046JCE, 8045JCE, 8044JCE, 8353JCE, 8352JCE, 8223JCE, 7779JCE, 7776SD, 7777SD, 7697HOB, 7776AD, 7992AD, 7992, 8483HD

New **FCC ID:** [2AON7-8702](#); Model Number: RT60, 8702, 8701, 8700, 8702ST, 8701ST, 8700ST, 7554CT, 8159CT, 6759-2, 6759HD-2, 7693HD, 7697HD, 7776HD, 7697HDC, 7752PS, 7697PS, 8149PS, 7776, 7777, 7778, 7779, 7776NR, 7777NR, 6759TJX, 7776TJX, 7778TJX, 7779TJX, 7992TJX, 8434TJX, 8016WM, 8017WM, 8062JCP, 8048JCP, 8047JCP, 8046JCP, 8045JCP, 8044JCP, 7776JCP, 7777JCP, 7778JCP, 7779JCP, 7992JCP, 8352JCP, 8353JCP, 8223JCP, 8062JCE, 8048JCE, 8047JCE, 8046JCE, 8045JCE, 8044JCE, 8353JCE, 8352JCE, 8223JCE, 7779JCE, 7776SD, 7777SD, 7697HOB, 7776AD, 7992AD, 7992, 8483HD

This is to advise and officially, that we, **TZUMI Electronics,LLC.**, hereby declare that the product name is same and only FCC ID difference as market requirement;  
The original test results continue to be representative of and applicable to the equipment of the new FCC ID;  
If you have any query, please feel free to contact me.

Sincerely,



Name: Ezra Azar  
Company: TZUMI Electronics,LLC  
Address: 16 EAST 34TH STREET 16TH FLOOR NEW YORK, NY 10016 United States  
Phone: 212-689-6008  
Fax: 212-684-3622  
E-Mail: Ezra@Tzumi.com