



Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:40:27

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:40:37

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:40:53

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:41:03

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:41:19

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:41:29

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:41:45

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:41:55

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:42:08

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:42:18

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:42:34

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:42:44

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:42:59

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:43:10

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:43:26

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:43:36

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:43:49

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:43:59

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:44:18

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:44:28

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:44:41

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:44:52

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:45:05

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:45:15

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:45:35

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:45:45

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:45:59

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:46:09

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:46:22

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:46:33

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:46:49

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:47:00

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:47:17

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:47:27

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:47:41

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:47:54

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:48:15

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:48:25

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:48:37

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:48:48

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:49:03

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:49:14

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:49:29

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:49:42

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:49:55

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:50:05

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:50:18

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:50:28

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:50:43

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:50:53

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:51:09

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:51:20

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:51:33

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:51:43

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:51:59

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:52:09

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:52:25

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:52:36

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:52:49

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:52:59

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:53:15

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:53:25

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:53:42

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:53:52

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:54:06

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:54:16

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:54:33

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:54:43

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:54:57

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:55:07

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:55:21

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.OCT.2022 19:55:31

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:55:53

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:56:03

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:56:19

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:56:29

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:56:42

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:56:52

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:57:08

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:57:18

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:57:34

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:57:45

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:58:01

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:58:11

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:58:27

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:58:38

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:58:54

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:59:05

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:59:18

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:59:29

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 19:59:45

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 19:59:55

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 20:00:09

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 20:00:19

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.OCT.2022 20:00:33

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 24.OCT.2022 20:00:43

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:27:47

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:27:57

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:28:13

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:28:24

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:28:36

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:28:47

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:29:02

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:29:15

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:29:28

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:29:38

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:29:51

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:30:01

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:30:17

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:30:28

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:30:44

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:30:54

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:31:39

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:31:49

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:32:03

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:32:13

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:32:26

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:32:36

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:32:54

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:33:04

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:33:20

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:33:30

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:33:46

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:33:57

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:34:12

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:34:23

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.OCT.2022 00:34:36

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.OCT.2022 00:34:46

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Date: 25.OCT.2022 00:34:59

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)



Date: 25.OCT.2022 00:35:10