



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 24.OCT.2022 19:16:14

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 24.OCT.2022 19:16:21

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 24.OCT.2022 19:16:29

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 24.OCT.2022 19:16:36

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 24.OCT.2022 19:16:47

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 24.OCT.2022 19:16:54

Band 2_3 MHz_High_QPSK_RB15#0




Date: 24.OCT.2022 19:17:03

Band 2_3 MHz_High_16QAM_RB15#0




Date: 24.OCT.2022 19:17:10

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 24.OCT.2022 19:17:21

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 24.OCT.2022 19:17:29

Band 2_5 MHz_High_QPSK_RB25#0




Date: 24.OCT.2022 19:17:38

Band 2_5 MHz_High_16QAM_RB25#0




Date: 24.OCT.2022 19:17:47

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 24.OCT.2022 19:18:00

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 24.OCT.2022 19:18:09

Band 2_10 MHz_High_QPSK_RB50#0




Date: 24.OCT.2022 19:18:19

Band 2_10 MHz_High_16QAM_RB50#0




Date: 24.OCT.2022 19:18:28

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 24.OCT.2022 19:18:43

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 24.OCT.2022 19:18:53

Band 2_15 MHz_High_QPSK_RB75#0




Date: 24.OCT.2022 19:19:04

Band 2_15 MHz_High_16QAM_RB75#0




Date: 24.OCT.2022 19:19:15

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 24.OCT.2022 19:19:29

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 24.OCT.2022 19:19:40

Band 2_20 MHz_High_QPSK_RB100#0




Date: 24.OCT.2022 19:19:52

Band 2_20 MHz_High_16QAM_RB100#0




Date: 24.OCT.2022 19:20:03

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 24.OCT.2022 19:20:16

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 24.OCT.2022 19:20:24

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 24.OCT.2022 19:20:31

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 24.OCT.2022 19:20:38

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 24.OCT.2022 19:20:49

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 24.OCT.2022 19:20:57

Band 4_3 MHz_High_QPSK_RB15#0




Date: 24.OCT.2022 19:21:05

Band 4_3 MHz_High_16QAM_RB15#0




Date: 24.OCT.2022 19:21:11

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 24.OCT.2022 19:21:23

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 24.OCT.2022 19:21:31

Band 4_5 MHz_High_QPSK_RB25#0




Date: 24.OCT.2022 19:21:40

Band 4_5 MHz_High_16QAM_RB25#0




Date: 24.OCT.2022 19:21:48

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 24.OCT.2022 19:22:01

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 24.OCT.2022 19:22:11

Band 4_10 MHz_High_QPSK_RB50#0




Date: 24.OCT.2022 19:22:21

Band 4_10 MHz_High_16QAM_RB50#0




Date: 24.OCT.2022 19:22:29

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 24.OCT.2022 19:22:44

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 24.OCT.2022 19:22:54

Band 4_15 MHz_High_QPSK_RB75#0




Date: 24.OCT.2022 19:23:05

Band 4_15 MHz_High_16QAM_RB75#0




Date: 24.OCT.2022 19:23:16

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 24.OCT.2022 19:23:31

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 24.OCT.2022 19:23:41

Band 4_20 MHz_High_QPSK_RB100#0




Date: 24.OCT.2022 19:23:53

Band 4_20 MHz_High_16QAM_RB100#0




Date: 24.OCT.2022 19:24:04

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 24.OCT.2022 19:24:19

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 24.OCT.2022 19:24:27

Band 7_5 MHz_High_QPSK_RB25#0




Date: 24.OCT.2022 19:24:36

Band 7_5 MHz_High_16QAM_RB25#0




Date: 24.OCT.2022 19:24:44

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 24.OCT.2022 19:24:57

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 24.OCT.2022 19:25:06

Band 7_10 MHz_High_QPSK_RB50#0




Date: 24.OCT.2022 19:25:16

Band 7_10 MHz_High_16QAM_RB50#0




Date: 24.OCT.2022 19:25:26

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 24.OCT.2022 19:25:40

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 24.OCT.2022 19:25:51

Band 7_15 MHz_High_QPSK_RB75#0




Date: 24.OCT.2022 19:26:02

Band 7_15 MHz_High_16QAM_RB75#0




Date: 24.OCT.2022 19:26:12

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 24.OCT.2022 19:26:28

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 24.OCT.2022 19:26:39

Band 7_20 MHz_High_QPSK_RB100#0




Date: 24.OCT.2022 19:26:50

Band 7_20 MHz_High_16QAM_RB100#0




Date: 24.OCT.2022 19:27:01

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 25.OCT.2022 00:18:14

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 25.OCT.2022 00:18:20

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 25.OCT.2022 00:18:27

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 25.OCT.2022 00:18:33

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 25.OCT.2022 00:18:44

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 25.OCT.2022 00:18:51

Band 12_3 MHz_High_QPSK_RB15#0




Date: 25.OCT.2022 00:18:58

Band 12_3 MHz_High_16QAM_RB15#0




Date: 25.OCT.2022 00:19:04

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 25.OCT.2022 00:19:14

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 25.OCT.2022 00:19:22

Band 12_5 MHz_High_QPSK_RB25#0




Date: 25.OCT.2022 00:19:29

Band 12_5 MHz_High_16QAM_RB25#0




Date: 25.OCT.2022 00:19:35

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 25.OCT.2022 00:19:47

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 25.OCT.2022 00:19:55

Band 12_10 MHz_High_QPSK_RB50#0




Date: 25.OCT.2022 00:20:03

Band 12_10 MHz_High_16QAM_RB50#0




Date: 25.OCT.2022 00:20:10

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 25.OCT.2022 00:20:23

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 25.OCT.2022 00:20:30

Band 17_5 MHz_High_QPSK_RB25#0




Date: 25.OCT.2022 00:20:38

Band 17_5 MHz_High_16QAM_RB25#0




Date: 25.OCT.2022 00:20:44

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 25.OCT.2022 00:20:55

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 25.OCT.2022 00:21:03

Band 17_10 MHz_High_QPSK_RB50#0



Date: 25.OCT.2022 00:21:11

Band 17_10 MHz_High_16QAM_RB50#0



Date: 25.OCT.2022 00:21:18