



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 17.FEB.2022 16:36:52

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 17.FEB.2022 16:37:13

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 17.FEB.2022 16:37:34

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 17.FEB.2022 16:37:55

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 17.FEB.2022 16:38:17

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 17.FEB.2022 16:38:35

Band 2_3 MHz_High_QPSK_RB15#0




Date: 17.FEB.2022 16:38:57

Band 2_3 MHz_High_16QAM_RB15#0




Date: 17.FEB.2022 16:39:14

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 17.FEB.2022 16:39:37

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 17.FEB.2022 16:39:58

Band 2_5 MHz_High_QPSK_RB25#0




Date: 17.FEB.2022 16:40:19

Band 2_5 MHz_High_16QAM_RB25#0




Date: 17.FEB.2022 16:40:40

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 17.FEB.2022 16:41:02

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 17.FEB.2022 16:41:22

Band 2_10 MHz_High_QPSK_RB50#0




Date: 17.FEB.2022 16:41:43

Band 2_10 MHz_High_16QAM_RB50#0




Date: 17.FEB.2022 16:42:03

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 17.FEB.2022 16:42:29

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 17.FEB.2022 16:42:57

Band 2_15 MHz_High_QPSK_RB75#0




Date: 17.FEB.2022 16:43:22

Band 2_15 MHz_High_16QAM_RB75#0




Date: 17.FEB.2022 16:43:49

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 17.FEB.2022 16:44:19

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 17.FEB.2022 16:44:46

Band 2_20 MHz_High_QPSK_RB100#0




Date: 17.FEB.2022 16:45:11

Band 2_20 MHz_High_16QAM_RB100#0




Date: 17.FEB.2022 16:45:36

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 17.FEB.2022 16:45:59

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 17.FEB.2022 16:46:23

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 17.FEB.2022 16:46:44

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 17.FEB.2022 16:47:05

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 17.FEB.2022 16:47:25

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 17.FEB.2022 16:47:42

Band 4_3 MHz_High_QPSK_RB15#0




Date: 17.FEB.2022 16:48:01

Band 4_3 MHz_High_16QAM_RB15#0




Date: 17.FEB.2022 16:48:19

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 19.FEB.2022 17:09:58

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 17.FEB.2022 16:48:56

Band 4_5 MHz_High_QPSK_RB25#0




Date: 18.FEB.2022 09:41:48

Band 4_5 MHz_High_16QAM_RB25#0




Date: 18.FEB.2022 09:49:34

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 17.FEB.2022 16:50:03

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 17.FEB.2022 16:50:23

Band 4_10 MHz_High_QPSK_RB50#0




Date: 17.FEB.2022 16:50:44

Band 4_10 MHz_High_16QAM_RB50#0




Date: 17.FEB.2022 16:51:04

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 17.FEB.2022 16:51:34

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 17.FEB.2022 16:51:58

Band 4_15 MHz_High_QPSK_RB75#0




Date: 17.FEB.2022 16:52:23

Band 4_15 MHz_High_16QAM_RB75#0




Date: 17.FEB.2022 16:52:51

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 17.FEB.2022 16:53:17

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 17.FEB.2022 16:53:45

Band 4_20 MHz_High_QPSK_RB100#0




Date: 17.FEB.2022 16:54:10

Band 4_20 MHz_High_16QAM_RB100#0




Date: 17.FEB.2022 16:54:34

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 17.FEB.2022 16:54:54

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 17.FEB.2022 16:55:11

Band 7_5 MHz_High_QPSK_RB25#0




Date: 18.FEB.2022 09:54:20

Band 7_5 MHz_High_16QAM_RB25#0




Date: 17.FEB.2022 16:55:51

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 17.FEB.2022 16:56:13

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 17.FEB.2022 16:56:32

Band 7_10 MHz_High_QPSK_RB50#0




Date: 17.FEB.2022 16:56:53

Band 7_10 MHz_High_16QAM_RB50#0




Date: 17.FEB.2022 16:57:13

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 17.FEB.2022 16:57:39

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 17.FEB.2022 16:58:07

Band 7_15 MHz_High_QPSK_RB75#0




Date: 17.FEB.2022 16:58:32

Band 7_15 MHz_High_16QAM_RB75#0




Date: 17.FEB.2022 16:58:56

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 17.FEB.2022 16:59:26

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 17.FEB.2022 16:59:51

Band 7_20 MHz_High_QPSK_RB100#0




Date: 17.FEB.2022 17:00:19

Band 7_20 MHz_High_16QAM_RB100#0




Date: 17.FEB.2022 17:00:46

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 17.FEB.2022 17:01:09

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 17.FEB.2022 17:01:30

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 17.FEB.2022 17:01:55

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 17.FEB.2022 17:02:16

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 17.FEB.2022 17:02:39

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 17.FEB.2022 17:03:00

Band 12_3 MHz_High_QPSK_RB15#0




Date: 17.FEB.2022 17:03:21

Band 12_3 MHz_High_16QAM_RB15#0




Date: 17.FEB.2022 17:03:42

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 18.FEB.2022 10:00:55

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 18.FEB.2022 09:59:50

Band 12_5 MHz_High_QPSK_RB25#0




Date: 18.FEB.2022 10:03:47

Band 12_5 MHz_High_16QAM_RB25#0




Date: 18.FEB.2022 10:05:55

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 17.FEB.2022 17:05:40

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 17.FEB.2022 17:06:03

Band 12_10 MHz_High_QPSK_RB50#0




Date: 17.FEB.2022 17:06:26

Band 12_10 MHz_High_16QAM_RB50#0




Date: 17.FEB.2022 17:06:46

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 18.MAY.2022 19:01:30

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 18.FEB.2022 10:30:25

Band 17_5 MHz_High_QPSK_RB25#0




Date: 18.FEB.2022 10:33:20

Band 17_5 MHz_High_16QAM_RB25#0




Date: 18.FEB.2022 10:32:07

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 17.FEB.2022 17:08:44

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 17.FEB.2022 17:09:04

Band 17_10 MHz_High_QPSK_RB50#0



Date: 17.FEB.2022 17:09:24

Band 17_10 MHz_High_16QAM_RB50#0



Date: 17.FEB.2022 17:09:47