



Please refer to following plots:

and 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:26:34

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:26:45

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:27:03

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:27:14

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:27:32

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:27:43

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:28:01

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:28:12

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:28:29

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:28:41

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:28:58

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:29:09

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:29:31

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:29:42

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:30:00

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:30:11

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:30:29

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:30:40

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:30:58

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:31:09

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:31:24

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:31:35

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:31:50

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:32:01

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:32:25

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:32:37

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:32:57

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:33:08

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:33:28

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:33:39

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:34:00

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:34:11

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:34:29

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:34:40

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:35:00

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:35:12

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:35:32

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:35:43

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:35:57

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:36:09

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:36:23

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:36:35

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:36:56

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:37:07

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:37:21

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:37:32

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:37:50

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:38:01

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:38:19

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:38:30

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:38:45

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:38:56

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:39:10

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:39:22

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:39:40

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:39:51

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:40:07

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:40:18

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:40:33

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:40:44

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:41:05

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:41:16

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:41:36

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:41:48

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:42:08

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:42:19

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:42:41

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:42:52

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:43:12

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:43:24

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:43:44

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.AUG.2022 19:43:55

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:48:57

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:49:08

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:49:26

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:49:37

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:49:52

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:50:03

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:50:22

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:50:33

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:50:48

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:50:59

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:51:15

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:51:26

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:51:51

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:52:02

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:52:20

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:52:31

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:52:49

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:53:00

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:53:25

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:53:37

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:53:58

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:54:10

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.SEP.2022 11:54:28

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.SEP.2022 11:54:39

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:44:42

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:44:53

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:45:07

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:45:18

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:45:36

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:45:47

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:46:05

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:46:16

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:46:30

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:46:41

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:46:55

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:47:06

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:47:24

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:47:35

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:47:53

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:48:04

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:48:22

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:48:33

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:48:51

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:49:02

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:49:17

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:49:28

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:49:46

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:49:58

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:50:18

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:50:29

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:50:43

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:50:54

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:51:12

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:51:23

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:51:44

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:51:56

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.AUG.2022 19:52:14

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.AUG.2022 19:52:25

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Date: 27.AUG.2022 19:52:40

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)



Date: 27.AUG.2022 19:52:51