

Frontiir Pte (with Frontiir Co LTD, Myanmar)
809 Yakima Drive,Fremont, CA 94539,United States.

Date: January 13, 2021

FCC ID: 2AQLF-SD5BGX

Model Number: SD5BGD,SD5BGX("X" on behalf of one of 26 English Letters A-Z)

To:
Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD

To Whom It May Concern,

We, **SD5BGD,SD5BGX("X" on behalf of one of 26 English Letters A-Z)**, declare that this EUT (FCC ID: 2AQLF-SD5BGX) doesn't have Ad Hoc mode function on "non-US/Canada frequencies". In addition, the frequency selection feature is disabled by firmware for devices marked to the US/Canada. For DTS part of this device, only channels 1-11 will be used in North America, Country code selection is disabled.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely,

Allen Miu

Signature

Allen Miu

Frontiir Pte (with Frontiir Co LTD, Myanmar)