





NTNV_DC_13A_n77A-3700-3980_PC3_30_5+80
 _M+L_TID21_NS_01_0.009_0.15_#1




NTNV_DC_13A_n77A-3700-3980_PC3_30_5+80
 _M+L_TID21_NS_01_30_1000_#1


















NTNV_DC_13A_n77A-3700-3980_PC3_30_5+80_M+M_TID16_NS_01_6000_26000_#1

NTNV_DC_13A_n77A-3700-3980_PC3_30_5+80_M+M_TID16_NS_01_26000_40000_#1



NTNV_DC_13A_n77A-3700-3980_PC3_30_5+80_M+M_TID17_NS_01_0.009_0.15_#1

NTNV_DC_13A_n77A-3700-3980_PC3_30_5+80_M+M_TID17_NS_01_0.15_30_#1

