




NTNV_DC_13A_n77A-3700-3980_PC3_30_5+90
 _M+L_TID20_NS_01_0.009_0.15_#1




NTNV_DC_13A_n77A-3700-3980_PC3_30_5+90
 _M+L_TID20_NS_01_30_1000_#1





















NTNV_DC_13A_n77A-3700-3980_PC3_30_5+90
 _M+M_TID19_NS_01_30_1000_#1

NTNV_DC_13A_n77A-3700-3980_PC3_30_5+90
 _M+M_TID19_NS_01_1000_6000_#1



NTNV_DC_13A_n77A-3700-3980_PC3_30_5+90
 _M+M_TID19_NS_01_6000_26000_#1

NTNV_DC_13A_n77A-3700-3980_PC3_30_5+90
 _M+M_TID19_NS_01_26000_40000_#1



