


## Elettronica GF s.r.l.

Via Ca Bianca, 10 - 48018 - FAENZA (RA) ITALY







March 05, 2020

Attn: Reviewing Engineer

**Federal Communication Commission** 

7435 Oakland Mills Road

Columbia, MD 21046

Object: Class II Permissive change request for NFC/BLE (Gymkit) 5V RS232 board

FCC ID: 2ARDN0615E

HVIN: 0615G

This Letter serves as an official request for FCC approval of a class II Permissive Change for NFC/BLE (Gymkit) 5V RS232 board.

The reason for the Class II permissive change is the replacement of Apple MFI337S3959 – Mfi coproc. V2.0C with IC MFi Coproc. 3.0 MFI343S00177. The replacement is needed because Apple MFI337S3959 – Mfi coproc. V2.0C is in state End of Life and the replacement indicated from productor is MFi Coproc. 3.0 MFI343S00177. The functions are the same between 2 IC, and not are related with radio functions.

## Please Refer to schematic "tg^jsc0615\_g01.beta1.pdf", the section changed is reference U2

The laboratory tests are necessary in order to demonstrate that the board remains compliance with FCC rules.

Sincerely,

David Sabbatani

Elettronica GF s.r.l.

Mard foll