




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM QPSK_3690MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM QPSK_3690MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM QPSK_3690MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM QPSK_3690MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3690MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3690MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM QPSK_3690MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM QPSK_3690MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3690MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3690MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Outer_Full




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3560.01MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3560.01MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3560.01MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3560.01MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3560.01MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3690MHz_Edge_1RB_Right



n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3690MHz_Edge_1RB_Right



n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3690MHz_Edge_1RB_Right



n48_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3690MHz_Edge_1RB_Right

