




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3624.99MHz_Edge_1RB_Left

