
REPORT NO: 12489879 DATE: 2019-01-14 FCC ID: 2ARYO-EB10 IC: 24573-EB10


11. **SETUP PHOTOS**

RADIATED EMISSION BELOW 30 MHz



REPORT NO: 12489879 DATE: 2019-01-14 FCC ID: 2ARYO-EB10 IC: 24573-EB10

RADIATED EMISSION ABOVE 30 MHz



333 Pfingsten Rd., Northbrook, IL 60062, USA

This report shall not be reproduced except in full, without the written approval of UL LLC TEL: (847) 272-8800 REPORT NO: 12489879 DATE: 2019-01-14 FCC ID: 2ARYO-EB10 IC: 24573-EB10

AC MAINS LINE CONDUCTED EMISSION




333 Pfingsten Rd., Northbrook, IL 60062, USA

This report shall not be reproduced except in full, without the written approval of UL LLC

REPORT NO: 12489879 DATE: 2019-01-14 FCC ID: 2ARYO-EB10 IC: 24573-EB10

FREQUENCY TOLERANCE OVER EXTREME CONDITIONS



END OF REPORT

FORM NO: CCSUP4701I