

panoramaxx



...COMM

Maxximize your horizon.

• optrel®
swiss made



Notes:

QUICK START GUIDE..4

FUNCTIONS 6

SPARE PARTS 8

ENGLISH 11

DEUTSCH 13

FRANÇAIS 14

SVENSKA 16

ITALIANO 17

ESPAÑOL 19

PORTUGUÉS 20

NEDERLANDS 22

SUOMI 23

DANSK 25

NORSK 26

POLSKI 28

ČEŠTINA 29

中文 31

MAGYAR 32

TÜRKÇE 34

日本語 35

ΕΛΛΗΝΙΚΑ 37

БЪЛГАРСКИ 38

SLOVENSKY 40

SLOVENSKO 41

ROMÂNĂ 43

EESTI 44

LIETUVIŠKAI 46


LATVIEŠU 47

РУССКИЙ 49

HRVATSKI 50


GAEILGE 52

MALTI 53


1

charging

- Low battery (blinking)
- Charging battery
- Fully charged battery

2**6**

Bluetooth grinding



QUICK START GUIDE

5

welding



- | | | |
|---|--------------|---|
| <p>Auto mode
</p> <p>Sensitivity
</p> <p>choose sensitivity</p> | <p>Delay</p> | <p>choose Auto & shade level correction</p> |
| <p>Manual mode
</p> <p>Sensitivity
</p> <p>choose sensitivity</p> | <p>Delay</p> | <p>choose Manual & shade level</p> |

4

front/inside cover lens exchange

