



Pin configuration



Pin No	Pin assignment
1	Feed termination
2	Feed point mark
3	Solder termination

Dimensions



Symbol	Dimensions (mm)
A	16.00 ± 0.10
B	3.10 ± 0.10
C	0.60 ± 0.05
H	1.65 ± 0.20

PCB foot printer

